

30.04.21

1-40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20
1	FRONT BUMPER GRILLE /LH			\$187.20
1	FRONT RAD GRILLE			\$1,480.00
1	FRONT BUMPER BRACKET TOP /LH			\$22.40
1	FRONT BUMPER BRACKET LH			\$24.60
1	BONNET COVER			\$2,265.90
1	FRONT FENDER LH			\$663.00
1	FRONT FENDER SHIELD /LH			\$174.90
1	HEAD LAMP ASSY LH			\$1,800.00
1	HEAD LAMP SUPPORT PANEL			\$907.40
1	FRONT WHEEL CAP LH			\$217.20
10	BUMPER CLIPS			\$22.20
	SUB TOTAL		7482.60	\$8,797.00
	LESS 20%		5986.08	\$1,759.40
				\$7,037.60
	Labour Charge			
	Panel Beating		585	\$900.00
	Spray Painting Charge		750	\$800.00
	Remove/refix air con & charge in gas		100.00	\$120.00
	Tuff Kote		40	\$80.00
	Check Lighting		30	\$60.00
	TOTAL LABOUR		1345	\$1,960.00
	ESTIMATE TOTAL		7331.08	\$5,626.16
			4585	
			# 3 days	

Tanphi 9749 5749 'WP'
 3/5/21 R 1pm 2-30
 L/S Resurvey after repair
 Tanphi & Whantown

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: