



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS/AWA21005481/Avf3e2 Date: 24/08/2021 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 726U	Veh. Inspected	SMY 8599B
Policy No.	BVFCB0013732001	Coverage (\$)	0.00
Claim No.	NSV2100059/HLF	Excess (\$)	0.00
Assign From	STELLA GOH	Assign Date	05/05/2021
2. Vehicle Particulars & Condition			
Make & Model	AUDI A6	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	WAUZZZF21MN050728	Colour	BRONZE
Odometer	817 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R18	MICHELIN	6 mm
L/H Front Tyre	225/55 R18	MICHELIN	6 mm
R/H Rear Tyre	225/55 R18	MICHELIN	6 mm
L/H Rear Tyre	225/55 R18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/04/2021	Inspection Date	06/05/2021
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	