

Survey
6/5/2021
1300 hrs
TGL
Mw

Resurvey done
on same day

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Company Reg No: 201929175W

Vehicle No: **GBK9447D**
Model and make: Toyota Hiace
Chassis No: JTFHT02P500251172

Qty Spare Parts

List Price (\$)

1	Rear bumper
1	Rear bumper LH side retainer
1	LH rear side panel
1	LH taillamp assy
1	LH taillamp lower garnish
1	LH taillamp lower garnish retainer
1	LH rear wheel cap
1	LH rear wheel
1	LH rear wheel bearing

\$	✓ 484.30 BR ✓
\$	✓ 66.10 NE ✓
\$	✓ 1,546.90 DD ✓
\$	✓ 364.80 BR ✓
\$	✓ 84.00 BR ✓
\$	52.00 NDX
\$	168.20
\$	440.20 } NDX
\$	159.00

	\$ 2,546.10	3,366.50
-25%	\$ 636.53	841.63
	\$ 1,909.58	2,524.88

Qty Spare Parts

Special Nett (\$)

1set Rear bumper clips

\$	30.00	60.00 NEC ✓
----	-------	------------------------

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$	600.00	1,000.00 ✓
----	--------	------------

Spray painting on affected panels

\$	400.00	950.00 ✓
----	--------	----------

Check wiring and lighting system

\$		60.00 NNX
----	--	----------------------

Apply rust coating on affected areas

\$		70.00 NNX
----	--	----------------------

Remove and reinstall rear inner boards and garnish to assist repairs

\$		120.00 NNX
----	--	-----------------------

Remove and reinstall rear bumper reverse sensor

\$	60.00	70.00 ✓
----	-------	--------------------

Conduct, test drive and adjust wheel alignment system

\$ ~~100.00~~ } NNX

Apply joint panels sealant on affected areas

\$ ~~60.00~~

Total:

\$ 5,014.88

1860.00

Lump sum repair
Repair days 5

PARTS	1,909.58
SN	37.00
LABOUR	<u>1,040.60</u>
	2,999.58
@ 20%	<u>599.92</u>
	2,399.60

L/S 2,400/2

TG Lim Lim

14/5/2021

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: