

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : PECK LEE LING
23 MAKEPEACE RD

SINGAPORE 228647

TEL: 91905525

ATTN:

Your Ref No: SLH9236T

Claim Type: Third Party → *Acc*

Accident Date: 03/05/2021

TP Veh Reg No: SCZ9118M

Estimate No: MC1901926

Date: 05 May 2021

Policy No: MP311278

Veh Reg No: SLH9236T

Make/Model: TOYOTA WISH 1.8 CVT

Not Authorized

61 Day & Resurvey After Rain

Estimate Repair Cost to Vehicle No :SLH9236T

4-5 days

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR WINDSCREEN MOULDING TOP	1 PC	<i>Mc</i> 61.70	<i>✓</i>
2 REAR WINDSCREEN MOULDING LH & RH	2 PC	<i>Mc</i> 139.08	<i>✓</i>
3 REAR WINDSCREEN MOULDING BTM	1 PC	<i>Mc</i> 70.20	<i>✓</i>
4 TAILGATE	1 PC	<i>B</i> 1,477.30	<i>✓</i>
5 TAILGATE EMBLEM	1 PC	<i>Mc</i> 65.70	<i>✓</i>
6 TAILGATE ELEGANCE LOGO	1 PC	<i>Mc</i> 45.30	<i>✓</i>
7 TAILGATE VALVEMATIC LOGO	1 PC	<i>Mc</i> 47.60	<i>✓</i>
8 TAILGATE LOCK	1 PC	<i>Mc</i> 412.70	<i>X</i>
9 TAILGATE INNER TRIMBOARD	1 PC	<i>Mc</i> 363.70	<i>X</i>
10 TAILGATE RUBBER	1 PC	<i>Mc</i> 334.50	<i>✓</i>
11 REAR BUMPER	1 PC	<i>B71 CM</i> 591.80	<i>✓</i>
12 REAR BUMPER REFLECTOR LH	1 PC	<i>Mc</i> 56.80	<i>✓</i>
13 REAR BUMPER SIDE RETAINER LH	1 PC	<i>CM</i> 97.40	<i>✓</i>
14 REAR BUMPER SIDE BRACKET LH	1 PC	<i>Mc</i> 53.80	<i>✓</i>
15 REAR BUMPER CLIPS	12 PC	<i>Mc</i> 54.00	<i>✓</i>
16 REAR BUMPER EXTENSION LH - CHECK PRICE	1 PC	0.00	<i>✓</i>
17 REAR END PANEL	1 PC	536.70	<i>✓</i>
18 REAR END PANEL GARNISH	1 PC	298.00	<i>✓</i>
		4,706.28	
	Less 25%	1,176.57	3,529.71
Special Nett			
19 REVERSE SENSOR	1 SET	<i>Mc</i> 200.00	<i>✓</i>
		200.00	200.00
LABOUR			
20 TO REMOVE AND REINSTALL FRONT/REAR WINDSCREEN.	1 PC	120.00	<i>✓</i>
21 TO REMOVE AND REINSTALL WIPER COMPARTMENT SUCH AS WIPER MOTORS AND WIPER BLADES.	1 PC	60.00	<i>✓</i>
22 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>501</i>
23 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	<i>✓</i>
24 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	<i>✓</i>
25 TO SPRAY TAILGATE, REAR BUMPER, REAR END PANEL, REAR FENDER LH	1 PC	800.00	<i>600</i>
		1,700.00	1,700.00

JKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company