

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR GBJ 2454 J

<u>List items</u>		
1 pc.	Front bumper	\$ 727.10
1 pc.	Front bumper LH inner bracket	292.10
1 pc.	LH headlamp	1,145.10
1 pc.	Front grille	673.10
1 pc.	Front grille centre "TOYOTA" logo	97.10
1 pc.	Front wiper panel	258.10
1 pc.	Front body panel	1,244.10
1 pc.	Front "DYNA" emblem	84.10
1 pc.	Front LH side mirror garnish	192.30
1 pc.	Front LH side mirror assy	695.40
1 pc.	Front LH corner panel	258.20
1 pc.	Front windscreen moulding	248.22
1 pc.	Dashboard assy	980.60
1 pc.	Air con low pressure house	509.00
1 pc.	Air con evaporator unit	1,089.00
1 pc.	Air con blower unit	1,135.10
1 pc.	Heater unit	2,017.10
1 pc.	Front LH door	1,450.45
1 pc.	Front LH door front pillar outer	485.10
1 pc.	Front LH door front pillar inner	405.00
1 pc.	Front LH door rear pillar	660.00
1 pc.	Front LH door inner lock	509.00
2 pcs.	Front LH door hinge (Top & bottom)	148.20
1 pc.	Front LH door checker	145.00
1 pc.	Front LH weatherstrip	169.40
1 pc.	Front LH door inner trim board	728.10
1 set.	Front LH door inner trim board clips	50.00
1 pc.	Front LH door glass	408.10
1 pc.	Front LH door glass outer moulding	115.10
1 pc.	Front LH door glass inner moulding	110.12
1 pc.	Front LH door glass regulator	395.00
1 pc.	Front LH door glass regulator motor	509.00
1 pc.	Front LH door glass channel	145.10
1 pc.	Front cabin rear railing	685.40
1 pc.	Front LH step panel	435.10
1 pc.	Front LH step garnish	218.10
		\$ 19,416.99
Less 25%		4,854.25
		\$ 14,562.74 \$ 14,562.74