



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : -

Date: 12th May 2021

Our Ref : CS/TP21005508/Kqce2

M/s Wei Lee Motor Works
Block 9 Sin Ming Industrial
Estate #01-32
Singapore 575644
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMG 6795J
ACCIDENT ON 04/04/2021**

Instruction was received to inspect the vehicle Reg. No. SMG 6795J. The inspection was conducted on 13/04/2021 at the premises of M/s Wei Lee Motor Works, Block 9 Sin Ming Industrial Estate #01-32, Singapore 575644.

The following vehicle information was recorded:

| | |
|----------------------|---------------------------------|
| Registration Number | : SMG 6795J |
| Make/Model | : Toyota Corolla Altis 1.6 Auto |
| Year of Registration | : 2012 |
| Body Colour | : Metallic Gold |
| Chassis Number | : MR053REE104128113 |
| Engine Capacity | : 1598 cc |

The vehicle sustained damages at the n/s front portion. The undercarriage and body structure affected due to collision. The Estimated repair cost of such vehicle is S\$20,000.00 (Sin Dollars: Twenty Thousand only.) (Details see photographs enclosed)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 19,500.00 (est)

Less: LTA Reimbursement Value (RV)

(S\$ 11,265.00)

Nett Liability

S\$ 8,235.00

S\$ 8,235.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 20,000.00

Nett Liability

S\$ 20,000.00

(a) – (b) =

(S\$ 11,765.00)

The amount of estimated saving of S\$11,765.00 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:

KSC

KONG SENG CHEONG
Licensed Appraiser

h

K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MDATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.