

05 May 2021

India International Insurance Pte Ltd

*Not within
1 Day &
Return After Paint
6 days*

Attn. : Motor Claim Department

Re : 1 Quotation
Vehicle SLT3693H (Peugeot 3008)

S/N	Description	Amount (S\$)
	Parts Replacement	
	Rear left fender <i>B1</i>	\$ 1,690.00
	Rear left fender ark trim <i>D14</i>	\$ 357.00
	Rear left wheel cowling	\$ 298.00
	Rear bumper <i>R</i>	\$ 1,320.00
	Rear bumper braket <i>R</i>	\$ 192.00
	Rear wheel hub	\$ 549.00
	Rear lower suspension cross member	\$ 1,880.00
	<i>Rear left wheel Rim. Not by ✓</i>	
		\$ 6,286.00
	less 5%	\$ 5,971.70
	Labour Charges	
	To do 4 wheel alignment	\$ 120.00
	Remove quarter glass and refix	\$ 60.00
	To dismantle, cut out rear fender. To panel beat, reshape, straighten, orientate and align repair/replacement parts.	\$ 1,400.00
	To remove and refix, interior upholstery to facilitate repair.	\$ 180.00
	To rustproof all affected portion after repair.	\$ 100.00
	Remove and refix suspension	\$ 200.00
	Supply spray paint material and spray paint on necessary items and the affected area.	\$ 800.00
	Total:	\$ 8,831.70

*✓
✓
?
X
X
?
?

601
✓
700
100
301
?
660*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Block 176 #03-06 Sin Ming Drive Singapore 721
Tel: 64552237 Fax: 64556384

Acknowledged by Repairer:
Signature: _____