

LOH HENG

Automotive Repair Services
Accident Insurance Claims

05 May 2021

India International Insurance Pte Ltd

*Not within
L1 Rep & 4250h
Recovery After Paint
6day*

Attn. : Motor Claim Department

Re : | Quotation

Vehicle SLT3693H (Peugeot 3008)

S/N	Description	Amount (\$S)
	Parts Replacement	
	Rear left fender <i>1316</i>	\$ 1,690.00
	Rear left fender ark trim	\$ 357.00
	Rear left wheel cowling	\$ 298.00
	Rear bumper	\$ 1,320.00
	Rear bumper braket	\$ 192.00
	Rear wheel hub	\$ 549.00
	Rear lower suspension cross member <i>1720</i>	\$ 1,880.00
	<i>Rear left wheel Rim. with 230mm</i>	\$ 6,286.00
	less 5% <i>10%</i>	\$ 5,971.70
	Labour Charges	
	To do 4 wheel alignment	\$ 120.00
	Remove quator glass and refix	\$ 60.00
	To dismantle, cut out rear fender. To panel beat, reshape, straighten, orientate and align repair/replacement parts.	\$ 1,400.00
	To remove and refix, interior upholstery to facilitate repair.	\$ 180.00
	To rustproof all affected portion after repair.	\$ 100.00
	Remove and refix suspension	\$ 200.00
	Supply spray paint material and spray paint on necessary items and the affected area.	\$ 800.00
	Total:	\$ 8,831.70

*✓
✓
✓
X
X
✓
✓*

*601
✓
700
100
301
1801
6601*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurers Company

Block 176 #03-08 Sin Ming Drive Singapore 721
Tel: 64552237 / 64550797 Fax: 64556384

Acknowledged by Repairer:
Signature:
Date: