

Mechanical Inspection Requests

Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>

Fri 5/3/2021 6:41 PM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Muhd Farhan SAIRI (SPF) <Muhd_Farhan_SAIRI@spf.gov.sg>; Adrian LIM (SPF) <Adrian_LIM@spf.gov.sg>; Abdul Rahim SALIM (SPF) <Abdul_Rahim_SALIM@spf.gov.sg>; Jun Yan TAN (SPF) <TAN_Jun_Yan@spf.gov.sg>; Chin Loong NEO (SPF) <NEO_Chin_Loong@spf.gov.sg>; Arman MOHAMMED ALI (SPF) <Arman_Mohammed_Ali@spf.gov.sg>; Chwee Theng NG (SPF) <NG_Chwee_Theng@spf.gov.sg>

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **8 vehicles** below. Those in **red** are deemed to be **urgent**:

-
- a. **Case IAFP-IB-2021305 - Mechanical Inspection of Motorcar, SJR6883R (TP/IP/08593/2021)**
- b. **Case IAFP-IB-2021305 - Mechanical Inspection of Motorcycle, JRS1004 (TP/IP/08593/2021)**
- c. **Case IAFP-IB-2021305 - Mechanical Inspection of Motorcar, SLL2295Y (TP/IP/08593/2021)**
-

On 18 February 2021 at about 2306 hrs, the motorcycle, JRS1004 was travelling along KJE (PIE) 2.5 km on lane 2 of the 3-lane road. While travelling straight, the said motorcycle suddenly veered to the left and hit onto the right side mirror of motorcar, SJR6883R, that was travelling on lane 3. The impact caused the motorcycle to fall on lane 2. Subsequently, the motorcar, SLL2295Y that was travelling on lane 2, collided onto the motorcyclist who was ahead of him. As a result of the accident, the motorcyclist was conveyed to KTPH unconscious as he sustained serious head injuries and bodily abrasions. A detailed mechanical inspection is required to rule out mechanical default.

Vehicle to be inspected: **SJR6883R** - Driver (Involved Party)
 JRS1004 - Rider (Potential Defendant / Victim)
 SLL2295Y - Driver (Potential Defendant)

IO In-Charge: IO Muhd Farhan Sairi

-
- d. **Case IAFP-IB-2021305 - Mechanical Inspection of Garbage Truck, XE4186K (TP/IP/07797/2021)**

On 14 February 2021 sometime before 12.15 p.m., the Accused was driving his Garbage Truck along Taman Kembangan on the single lane two way road when he failed to keep a proper lookout, collided onto the Deceased who was walking across the road from his left to right, causing the Deceased to fall onto the road and the Deceased's leg to be ran over by the Deceased's front right tyre. Deceased sustained multiple injuries and was conveyed to CGH by the ambulance. Deceased was pronounced dead on the 21 February 2021. at 12.20pm at CGH.

Vehicles to be inspected: **XE4186K** - Driver (Potential Defendant)

IO In-Charge: SIO Adrian Lim

- e. **Case IAFP-IB-2021305 - Mechanical Inspection of Taxi, SHC3328A (TP/IP/09811/2021)**

On 24 February 2021 sometime before 12.22 p.m., the Accused was driving his motor taxi along Jalan Ahmad Ibrahim at the junction of Benoi Road when he made a right turn into Benoi Road, causing the left side of his Taxi to be collided by a lorry, which was proceeding straight on the opposite direction on green light. Taxi driver claimed he could not recall what took place. Passenger of taxi who was seated at the rear left passenger seat was conveyed by AB to NTFGH with multiple injuries. She succumbed to her injuries and passed away on the 27 February 2021 at 10.56pm at NTFGH.

Vehicles to be inspected: **SHC3328A** - Driver (Potential Defendant)

IO In-Charge: SIO Adrian Lim

f. Case IAFP-IB-2021305 - Mechanical Inspection of Motor Car, SMC8216Y (TP/IP/06549/2021)

On 4 February 2021 at about 6.41 p.m., an accident took place between a motor car and a motor van along Tampines Expressway towards the direction of Pan Island Expressway, slip road into Pasir Ris Drive 8. Further investigation revealed that driver of the motor car claim that his brake was faulty as such resulted in the collision with a stationary motor van. Head Investigation directed for motor car to be inspected to eliminate mechanical fault or any possible defence raised by the defendant.

Vehicle to be inspected: **SMC8216Y** - Driver (Potential Defendant)

IO In-Charge: SIO Abdul Rahim

g. Case IAFP-IB-2021305 - Mechanical Inspection of Motor Car, SLL9438G (TP/IP/55797/2020)

On 16 December 2020 at about 7.46 p.m., an accident took place between a motor car and government property along Kallang Paya Lebar Expressway towards the direction of Tampines Expressway, slip road into Buangkok East Drive. Further investigation revealed that driver of the motor car claim that his brake was not responding as such resulted in him losing control of his motor car and collided onto government property. Head Investigation directed for motor car to be inspected to eliminate mechanical fault or any possible defence raised by the defendant.

Vehicle to be inspected: **SLL9438G** - Driver (Potential Defendant)

IO In-Charge: SIO Abdul Rahim

h. Case IAFP-IB-2021305 - Mechanical Inspection of Van, GBD4923R (TP/IP/09045/2021)

On 21 February 2021 at about 6.18 p.m., the driver of van, GBD4923R, had made a right turn from Tampines Central 2 onto Tampines Avenue 5 and failed to keep a proper lookout resulting in an accident with a pedestrian, who was crossing from the driver's left to right when the pedestrian crossing was showing green man. Due to the accident, the pedestrian sustained serious injury where he remained in vegetative state for a long period of time. A detailed mechanical inspection is required to rule out mechanical default.

Vehicle to be inspected: **GBD4923R** - Driver (Potential Defendant)

IO In-Charge: IO Jeff Tan

2. These request has been approved by my management.

3. Thank you, Sirs.

cc: IO Farhan, SIO Adrian, SIO Rahim and IO Jeff Tan, as requested by you
Bryan, OC GIT A, OC GIT D and OC GIT E, fyip

Best regards,

Kamaliah Kamis (Miss)

Senior Investigation Officer | Fatal Accident Investigation Team

Traffic Police Department | Singapore Police Force

DID: (65) 6547 6435 | FAX: (65) 6547 6352

