

REF: C721

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A
#02-03 AMK AUTOPOINT 568047
Tel No. : 64837111 Fax No. : 64837221
E-Mail : guanhinmotor@yahoo.com
Buss. Reg. No. : 06035200X

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD
190 CLEMENCEAU AVENUE
#03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924

Attention : Motor Claim Department
Contact : 62212111

Estimate : ES000940

Date : 12/05/2021
Vehicle Num. : SJB 2681 S
Make/Model : HONDA CIVIC 1.8L A-2007
Chassis/Eng# : JHMFD16308S21186/R18A13018390
Accident Date : 04/05/2021
Claim No. :
Reference :
Policy No. : (07/01/2008)

Not Authorised
1/1 Sep @ 2000p
Resurvey After Pain
3 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1. 1 LIST ITEMS :
2. 1 FRONT BUMPER
3. 1 FRONT BUMPER SIDE RETAINER LH
4. 1 FRONT LH FENDER INNER SHIELD
5. 1 FRONT LH LOWER ARM
6. 1 FRONT LH SHOCK ABSORBER
7. 1 FRONT KNUCKLE ARM BEARING LH
8. 1 FRONT LH KNUCKLE ARM

List Total S\$:

Net / Cost
638.00
45.00
150.00
243.00
259.00
166.00
305.00
200
1,806.00

1. 1 SPECIAL NETT ITEMS :
2. 1 TYRE
3. 10 SPORT RIM
3. 10 FENDER INNER SHIELD CLIP

Special Nett Total S\$:

Net / Cost
380.00
480.00
20.00
2.00
880.00

- LABOUR :
- REMOVE & FIX BACK FRONT BUMPER AND INNER SHIELD
- REMOVE & FIX BACK UNDERCARRIAGE
- WHEEL ALIGMENT
- SPRAY PAINTING
- Labour Total S\$:

200p
250.00
450.00
180.00
300.00
1,180.00

E. & O.E.

Total S\$: 3,866.00



for GUAN HIN MOTOR WORKSHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company