

## Hui Zhen (LKK Auto)

---

**From:** Bryan Ang (LKKAuto)  
**Sent:** Tuesday, 18 May 2021 2:36 pm  
**To:** Hui Zhen (LKK Auto)  
**Cc:** Shiau Chan (LKKAuto)  
**Subject:** RE: SMS 7625Y SURVEYED BY MR LIM

Hi HZ

KIV.

Total 37 photos uploaded in VIEWS and Merimen. No photos of undercarriage parts uploaded. Please get Mr Lim to upload.

If there are no photos, all undercarriage parts and related labour to remove.

Best Regards,

**Bryan Ang**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [bryanang@lkkauto.com](mailto:bryanang@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hui Zhen (LKK Auto) <[huizhen@lkkauto.com](mailto:huizhen@lkkauto.com)>

**Sent:** Monday, 17 May 2021 3:32 PM

**To:** Bryan Ang (LKKAuto) <[bryanang@lkkauto.com](mailto:bryanang@lkkauto.com)>

**Cc:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>

**Subject:** SMS 7625Y SURVEYED BY MR LIM

Dear Bryan,

For your audit.

Best Regards,

**Hui Zhen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [huizhen@lkkauto.com](mailto:huizhen@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)