



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21005557/R1tf3e2	
			Date: 26/10/2021	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKJ 23B
	Policy No.	DHOM120036701801	Coverage (\$)	0.00
	Claim No.	M12D15652105	Excess (\$)	10,000.00
	Assign From	JOSEPHINE WONG	Assign Date	06/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	ASTON MARTIN DB11	c.c	5204
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	SCFRLFAV0HGL02730	Colour	GREY
	Odometer	19643 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/40Z R20	PIRELLI	6 mm
	L/H Front Tyre	255/40Z R20	PIRELLI	6 mm
	R/H Rear Tyre	255/40Z R20	PIRELLI	6 mm
	L/H Rear Tyre	255/40Z R20	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/04/2021	Inspection Date	10/05/2021
	Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		
5a. Remarks				
	A)THE MARKET VALUE IS S\$543,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	