

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref:	CS/MSG21005567/Dtf3
4 SHENTON WAY #21-01,SGX CENTRE 2			Date:	06/05/2021
SINGAPORE 068807			Code:	MSG
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 7292Y	Veh. Inspected	SHD 4723E	
Policy No.	29145180ACX	Coverage (\$)	0.00	
Claim No.	635762	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY MEI LING)	Assign Date	06/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c 0			
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/05/2021	Inspection Date	07/05/2021	
Survey held at	Blk 9 Sector C, #01-42 Sin Ming Industrial Estate,			
Repairer	BIFROST AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				