



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

MS FIRST CAPITAL INSURANCE LTD		NAME : Ms Leong Nyet Ken	WIP : 33548
36 ROBINSON ROAD		ADDRESS : 2 Lorong Pisang Batu	EXCESS :
#16-01		Singapore 597929	DATE: 29-Apr-21
CITY HOUSE SINGAPORE 068877		TEL : 97324863	
ATTN. :			
FAX :			

VEH NO :	SKC1866R	DATE IN :		CONTACT PERSON :	Jess 8128 9802
CHASSIS NO :	JM6DK2W7AK0416088	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	CX3	DATE REG:	14-Aug-19	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	PART NO.	QTY	1st	2nd	REVISED	PRICES
1	MASCOT,REAR	MD11B-51-730	1		-	54.30
2	ORNAMENT	MD10J-51-771A	1		-	56.60
3	ORNAMENT,CAR NAME-REAR	MD10J-51-721	1		-	55.70
4	REAR BUMPER	MDHYF-50-22XABB	1		-	1,088.40
5	PIN,LOCATOR	MD10J-50-1K5	1		-	3.90
6	BRACKET,REAR @ 26.10-NECESSARY	MD10J-50-271	2		-	52.20
7	FASTENER @ 3.00-NECESSARY	MB45A-56-146A	10		-	30.00
8	GROMMET @ 2.70-NECESSARY	MBHN1-50-0Z1A	6		-	16.20
9	PAD @ 7.60-NECESSARY	MBR5S-56-994	2		-	15.20
10	REINF.,REAR	MDB2P-50-260A	1		-	362.80
11	RETAINER LH,REAR	MD10J-50-2J1B	1		-	24.60
12	RETAINER RH,REAR	MD10J-50-2H1B	1		-	24.60
13	TAPE @ 3.50-NECESSARY	MG043-62-864A	2		-	7.00
14	COVER,UNDER	MD10J-50-C51	1		-	42.60
15	GUARD	MD10J-50-371	1		-	17.10
16	CLIPS @ 2.90-NECESSARY	MBGV4-56-145	6		-	17.40
17	PAD @ 7.80-NECESSARY	MG001-67-061	2		-	15.60
18	SENSOR,ULTRASONIC -CENTER @ 200.50	MGM C8-67-UC1	2		-	401.00
19	CORD,SHORT ULTRASONIC	MD24H-67-SH0	1		-	119.70
TOTAL PARTS						2,404.90
TOTAL PARTS COST						2,404.90

Labour Description

1	MZ-BR-REAR02	REPLACE REAR BUMPER. REPAIR TAILGATE AND AREAS AFFECTED BY THE ACCIDENT.	-	1,320.00
---	--------------	--	---	----------

	TOTAL LABOUR		3,985.00
	TOTAL PARTS		2,404.90
	TOTAL		6,389.90
	LESS EXCESS		-
	TOTAL AFTER EXCESS		6,389.90
	GST 7%		447.29
	GRAND TOTAL		6,837.19

SUPPLEMENTARY LABOUR DESCRIPTION				
1		#N/A		-
2		#N/A		-

REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT TAKE NOTE THAT SHOULD YOU DECIDE	TRANS EUROKARS PTE LTD
---	-------------------------------

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT TAKE NOTE THAT SHOULD YOU DESIRE

BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature