

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21005586/UTF3E2

**Date:** 21/05/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900120027
<b>Claimant Vehicle No :</b>	SKC1223X	<b>Insured Vehicle No :</b>	SMM7730H
Date of Loss:	06/05/2021	Nature of Claim:	TP
		Claim No:	6481801165SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC1223X	Engine No:	R18A2102467
Make & Model:	HONDA STREAM, 1.8 X (A)	Chassis No:	RN63102332
Reg. Date:	23/07/2011 (Man. Year: 2009)	Odometer:	198324 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Linglong 6 mm	Rear Left Side:	Linglong 6 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Linglong 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	07/05/2021	
Date Inspected:	07/05/2021 Inspected At:	Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE Singapore 417807
Estimated Period of Repair:	0.0 days	

**Adjuster:** MARCUS CHUA

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$13,500.00
OMV :	\$21,140.00
PARF Rebate (1) :	\$10,570.00
Quota Premium Paid :	\$57,494.00
COE Rebate (2) :	\$1,156.00
Total Rebate (1) + (2) = :	\$11,726.00

The total amount incurred will be Market Value \$13,500.00 minus Total Rebate \$11,726.00 = \$1,774.00

# REPAIR DETAILS

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >