



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
 TEL: 6256 3561 FAX: 6256 4315
 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Ref: CS/CTI21005596/T1f3 Date: 07/05/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLG 9517M	Veh. Inspected	SLE 4323Z
Policy No.	DMHCSNA00004132000	Coverage (\$)	0.00
Claim No.	SNM21D202646/C2/IRENE	Excess (\$)	0.00
Assign From	IRENE TAY	Assign Date	07/05/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	04/05/2021	Inspection Date	10/05/2021
Survey held at	KENT SENG CAR SERVICES 1017 YISHUN INDUSTRIAL PARK A, #01-240, YISHUN INDUSTRIAL PARK A, SINGAPORE 768759		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			