

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0374/2021/HR
DATE : 30-Apr-21
WIP : 25403

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 5/5/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. MELVIN HEN YAK WEE
ADDRESS : 298A COMPASSVALE STREET
#15-172
SINGAPORE 541298
TELEPHONE : HP +65 96904614
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100285801-09
VEHICLE NO : **SDQ 6680 K**
MODEL CODE : A6 C7 2.0 TFSI MU 4G
MODEL YEAR : 12/1/2012
ENGINE NO : CDN 241282
CHASSIS NO : WAUZZZ4G8CN083559
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Apr-21
PLACE OF ACCIDENT : NEAR 28 SIN MING LANE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDQ 6680 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280
2	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS.	S/N \$ 980.00	X
3	TO DISMANTLE AND RENEW LHS REAR DOOR AND LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	1500
4	TO RESPRAY LHS REAR DOOR, LHS SILL PANEL TRIM, LHS REAR FENDER, DOOR ENTRANCE AND LHS SILL PANEL.	\$ 4,500.00	2200
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	X
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 11,152.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDQ 6680 K

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR DOOR - LH <i>Dented</i>	1	\$	4,227.00	✓
2	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$	124.00	✓
3	REAR DOOR OUTER SEAL <i>new</i>	1	\$	231.00	✓
4	REAR DOOR BONDING AGENT ?	1	\$	29.00	?
5	REAR DOOR CLEANING SOLUTION ?	1	\$	68.00	?
6	REAR DOOR APPLICATOR <i>new</i>	1	\$	8.00	✓
7	REAR DOOR CATCH ?	1	\$	120.00	?
8	REAR DOOR OUTER SEAL <i>new</i> ?	1	\$	284.00	?
9	REAR DOOR ROCKER MOULDING <i>del</i>	1	\$	858.00	✓
10	REAR DOOR ATTACHMENT PARTS - ADHESIVE TAPES <i>new</i>	1	\$	16.00	✓
11	REAR DOOR ATTACHMENT PARTS - CLIPS <i>new</i>	1	\$	106.00	✓
12	REAR DOOR STONE GUARD FILM <i>new rec.</i>	1	\$	118.00	✓
13	REAR DOOR SILL TRIM STRIP <i>new</i>	1	\$	120.00	✓
14	REAR SIDE PANEL - LH <i>Repair</i>	1	\$	4,532.00	✓
14	STONE CHIP ?	S/N	\$	180.00	?
15	REAR RIM - LH <i>new</i>	S/N		TBC	✓
16	ACRYLIC SEALANT <i>new</i>	S/N	\$	180.00	✓
17	METAL FILLER POWDER <i>new</i>	S/N	\$	280.00	✓
18	CAVITY WAX	S/N	\$	140.00	✓
19	SUNDRIES ?		\$	250.00	?
TOTAL SPARE PARTS		:	\$	11,871.00	
TOTAL LABOUR CHARGES		:	\$	11,152.00	
GRAND TOTAL		:	\$	23,023.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *05/05/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 06 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT