

⏪	<	1 of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find Next
---	---	----------	---	---	---	---	------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLE TREE ANSON SINGAPORE 079914		Ref: CS/AWA21005615/Etf3 Date: 07/05/2021	Code: AWA
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 5695S	Veh. Inspected	GBB 4713R
Policy No.		Coverage (\$)	0.00
Claim No.	AVCPSB0064951905	Excess (\$)	0.00
Assign From	PEGGY CHAN	Assign Date	07/05/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	21/10/2019	Inspection Date	17/05/2021
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			