

3A Automobile Pte Ltd

No 120 Lower Delta Road #02-15 Cendex Centre Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

Date: 19-Oct-2017

Vehicles Number: SKD1838 S

Make and Model: Toyota Corolla Altis 1.6 Auto

Date Of Accident: 19-Oct-2017

AMERICAN INTERNATIONAL GROUP

78 Amoy Street

Singapore 069897

Attn: Motor Claim Department

Tel: 64191000

Fax: 68357416

Unit	List Items	Units	Price	Prices
1	pc Rear Boot <i>bt</i>		\$781.10	\$781.10
2	pc Rear Boot Hinges <i>X s/c</i>		\$172.45	\$344.90
1	pc Rear Weatherstrip <i>nee</i>		\$182.25	\$182.25
1	pc Rear Boot Top Lock <i>bt</i>		\$171.45	\$171.45
1	pc Rear Boot Bottom Lock <i>bt</i>		\$131.35	\$131.35
1	pc Rear Boot Toyota Logo <i>nee</i>		\$61.10	\$61.10
1	pc Rear Boot Wording <i>nee</i>		\$61.35	\$61.35
1	pc Rear Bumper <i>de</i>		\$581.45	\$581.45
2	pc Rear Bumper Side Retainer L/R <i>nee</i>		\$171.45	\$342.90
8	pc Rear Bumper Clips <i>nee</i>		\$12.90	\$103.20
2	pc Rear Bumper Reflector L/R <i>X s/c</i>		\$178.85	\$357.70
1	pc Rear Bumper Foam <i>cut</i>		\$181.60	\$181.60
1	pc Rear Bumper Rear End Panel <i>bt</i>		\$782.10	\$782.10
1	pc Rear LHS Tailamp Assy <i>X s/c</i>		\$374.45	\$374.45
1	pc Rear LHS Fender Shield <i>X s/c</i>		\$182.10	\$182.10
8	pc Rear LHS Fender Shield Clips <i>X s/c</i>		\$12.90	\$103.20
1	pc Rear Panel Top Covering <i>crn</i>		\$281.75	\$281.75
				\$5,023.95

3661.60
25%
2746.20

1	Set	Rear Reverse Sensor <i>nw</i>	Less
			25%
			(\$1,255.99)
			\$200.00
			\$3,967.96

s/n s/n-200

Labour Charges

	To Remove & Replace the Damaged Parts as Listed Above, including Reinstallments of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts	800	\$1,200.00
	To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint on Front Right Hand Side Door, & Right Side Bottom Side Skirt with Oven Spray Booth Facilities	800	\$1,800.00
	Total		\$6,167.96

1600

Yours faithfully,

3A Automobile Pte Ltd

Person to contact : Winnie

Mobilephone: 6223 1122

Hasul
Hp 90010068

8 days

W/S

24/10/17 @ 1230

Resurvey after repair

2746.20

2000.00

1600.00

4546.20

20%

3636.96

45-3,600

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: