

SMRT Recommendation										Surveyor Approval				
M Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	1	1,113.15	Replace ▾	su/
One Time Key In	Main			WHEEL HUB FRT	1	549.70	549.70	25.00	412.28	Replace	0	0	Check ▾	?
One Time Key In	Main			SHOCK ABSORBER BEARING, FRT LH/RH	1	34.00	34.00	25.00	25.50	Replace	0	0	Check ▾	?
One Time Key In	Main			SHOCK ABSORBER FRT/LH	1	394.20	394.20	25.00	295.65	Replace	0	0	Check ▾	?
One Time Key In	Main			SHOCK ABSORBER MOUNTNG FRT, RH/LH	1	193.80	193.80	25.00	145.35	Replace	0	0	Check ▾	?
One Time Key In	Main			STABILIZER BAR LINK FRT/RH/LH	1	195.00	195.00	25.00	146.25	Replace	0	0	Check ▾	?
One Time Key In	Main			STEERING KNUCKLE LH FRT	1	580.80	580.80	25.00	435.60	Replace	0	0	Check ▾	?
One Time Key In	Main			LOWER ARM FRT/LH	1	625.90	625.90	25.00	469.42	Replace	0	0	Check ▾	?
One Time Key In	Main			JOINT ASSY, LWR BALL	1	195.60	195.60	25.00	146.70	Replace	0	0	Check ▾	?
One Time Key In	Main			TIE ROD END LH	1	159.30	159.30	25.00	119.48	Replace	0	0	Check ▾	?
One Time Key In	Main			DOOR FRT/LH	1	894.40	894.40	25.00	670.80	Replace	1	0	Repair ▾	R
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	new/
Total Spare Part Cost									5,901.41	Surveyor Total		1,585.65		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									4,721.13	Final Sur Total		1,268.52		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail