

Tanjum

## ASSIGNMENT

Veh No: FBR 8622 J Yr Regn: 2020, Nov ✓

Type: M.Càr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha Triity. 155 cc 155

Colour Green A/C: Insured / Std / NI / NA

Sp. Reading      -J      T/Radio: Insured / Std / NI / NA

Eng/No:

G/No: ML BSG 381 0000 59475

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim. or

Tyre Size: F: 90/80RV4

R: 130 / 70 mmHg

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm 1 R/Bal. 5 mm

|        |    |        |    |
|--------|----|--------|----|
| L/Bal. | mm | L/Bal. | mm |
|--------|----|--------|----|

D.O.A. D.O.I. 10/5/21

Survey held at Atan. Nystorin

Des. of Damages: Fnt / Rear / O/S / NS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision..

Bathing week

GITA uploaded

☐: Prelim. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

       S + RS.    SI

Photos

000000

Add Fee:

☐ : Site Insp (\$ -)

Interview 18

Teach. Insp. (3)

                    

Page 106, Folio 116b:

**Lump Sum / EIS:**



# ATAN MOTORING SUPPLY PTE LTD

Blk 3006 Ubi Road 1, #01-368/370 Singapore 408700.

Tel: 67431351 Fax: 67432719 Email: annasimsl@yahoo.com.sg

Business Registration No. A03552/1989W

6 May 2021

AIG Singapore  
Motor Claim Department  
78 Shenton Way  
#07-16  
Singapore 079120

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FBR8622J (Yamaha Tri City 2019)

|       |                                 |         |       |
|-------|---------------------------------|---------|-------|
| 4 pcs | Emblem                          | 80.00   | nec ✓ |
| 1 pc  | Right Brake Lever               | 25.00   | bus ✓ |
| 1 pc  | Right Balancer                  | 25.00   | ant ✓ |
| 1 pc  | Handle Bar                      | 98.00   | ?     |
| 1 set | Side Mirror                     | 58.00   | ant ✓ |
| 1 pc  | Right Front Fork Shaft Complete | 550.00  | ?     |
| 1 pc  | Left Fork Arm                   | 178.00  | ?     |
| 1 pc  | Front Inner Cowling             | 28.00   | ant ✓ |
| 1 pc  | Left Front Mudguard             | 39.00   | ant ✓ |
| 1 pc  | Right Front Mudguard            | 39.00   | ant ✓ |
| 1 pc  | Left Front Mudguard Cover       | 25.00   | ant ✓ |
| 1 pc  | Right Front Mudguard Cover      | 25.00   | ant ✓ |
| 1 pc  | Front Inner Bracket             | 115.00  | ?     |
| 1 pc  | Left Front Cover                | 82.00   | ant ✓ |
| 1 pc  | Right Front Cover               | 82.00   | ant ✓ |
| 1 pc  | Left Front Outer Cover          | 38.00   | ant ✓ |
| 1 pc  | Right Front Outer Cover         | 38.00   | ant ✓ |
| 1 pc  | Right Front Signal Light        | 42.00   | ant ✓ |
| 1 pc  | Left Inner Cover                | 32.00   | ant ✓ |
| 1 pc  | Left Lower Floorboard Cover     | 44.00   | ant ✓ |
| 1 pc  | Right Lower Floorboard Cover    | 44.00   | ant ✓ |
| 1 pc  | Left Rear Cover                 | 48.00   | ant ✓ |
| 1 pc  | Right Rear Cover                | 48.00   | ant ✓ |
| 1 pc  | Seat Cover                      | 100.00  | ant ✓ |
| 1 pc  | Belt Cover                      | 48.00   | ant ✓ |
| 1 pc  | Air Box Cover                   | 50.00   | ant ✓ |
| 1 pc  | Exhaust Protector               | 33.00   | ant ✓ |
| 1 pc  | Rear Box 42L                    | 120.00  | ant ✓ |
|       | Body Alignment                  | 200.00  | ant ✓ |
|       | Labour                          | 350.00  | 200 ✓ |
|       | Tpt from Tp to Idac to Workshop | 120.00  | 200 ✓ |
|       | Sub total                       | 2804.00 |       |
|       | GST 7%                          | 196.28  |       |
|       | Total                           | 3000.28 |       |

Tanpin 97495741 / 62563561  
6/5/21 @ 1720

P/P Resurvey before paint, new parts  
5 days  
Tanpin @ Kuantan