

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Rparthiban, Theerthan

Date: 11 May 2021

**Preliminary Advice**

Vehicle No	: SKG235Y	Accident Date	: 07/05/2021
Make	: MITSUBISHI ASX	Policy No.	: 1700077964
Assignment Date	: 10/05/2021	Excess	: S\$0.00
Date of Inspection	: 10/05/2021	Est. Duration of Repair	: 4
Inspection At	: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

**Point of Impact / General Description of Damages**

Parts claimed are not consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,030.53
Revised Amount	:S\$	4,773.94
Check Items (Estimated)	:S\$	659.65
Total	:S\$	5,433.59

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	69,000.00
COE / PARF Rebate	:S\$	45,277.00
Salvage Value	:S\$	
Margin for Repair	:S\$	23,723.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :