

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722
 Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE :

Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SJW 6943 A**
 Model : Proton Exora
 Year : _____
 Chassis No : _____

After-Paint: _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front bumper	1	\$ 955.80	\$ X Ry 955.80
2	Front bumper side retanier RH	1	\$ 84.00	\$ X nn 84.00
3	Front fender RH	1	\$ 1,105.00	\$ Ry 1,105.00
4	Front fender inner cowling RH	1	\$ 344.00	\$ X nn 344.00
5	Front door RH	1	\$ 1,178.00	\$ bt 1,178.00
6	Front door black tape RH	1	\$ 58.00	\$ nn 58.00
7	Front door inner trimboard RH	1	\$ 897.60	\$ X nn 897.60
8	Rear door RH	1	\$ 1,065.00	\$ bt 1,065.00
9	Rear door black tape RH	1	\$ 58.00	\$ nn 58.00
10	Rear door inner trimboard RH	1	\$ 797.60	\$ X nn 797.60
11	Rear fender RH	1	\$ 1,268.50	\$ Ry 1,268.50
12	Rear fender inner cowling RH	1	\$ 166.00	\$ X nn 166.00
13	Rear fender side glass moulding	1	\$ 738.00	\$ X nn 738.00
14	Rear bumper	1	\$ 897.30	\$ Ry 897.30
15	Rear bumper side retanier	2	\$ 62.50	\$ X nn 125.00
16	Front knuckle arm RH	1	\$ 398.00	\$ X nn 398.00
17	Front knuckle arm bearing RH	1	\$ 245.50	\$ X bt 245.50
18	Front shock absorber RH	1	\$ 364.00	\$ X nn 364.00
19	Front lower arm RH	1	\$ 535.25	\$ X nn 535.25
20	Rear axle	1	\$ 948.00	\$ X nn 948.00
21	Rear knuckle arm bearing RH	1	\$ 135.00	\$ bt nn 135.00
22	Rear shock absorber RH	1	\$ 319.60	\$ X nn 319.60

Parts Sub Total : \$ 12,683.15
 Discount 10% : \$ 1,268.32
PARTS TOTAL : \$ 11,414.84

2739.50
 10% - 2465.55

Nos.	SPECIAL NETT ITEMS	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ X 80.00
2	Front bumper clips	1	\$ 50.00	\$ X 50.00
3	Front fender sealant	1	\$ 100.00	\$ X 100.00
4	Front fender inner cowling clips	1	\$ 50.00	\$ X 50.00
5	Front door sealant	1	\$ 100.00	\$ X 100.00
6	Front door inner trimboard clips	1	\$ 50.00	\$ X 50.00
7	Rear door sealant	1	\$ 100.00	\$ X 100.00
8	Rear door inner trimboard clips	1	\$ 50.00	\$ X 50.00
9	Rear fender sealant	1	\$ 100.00	\$ X 100.00
10	Rear fender inner cowling clips	1	\$ 50.00	\$ X 50.00
11	Rear fender side glass sealant	1	\$ 100.00	\$ X 100.00
12	Rear fender side glass inner seal	1	\$ 60.00	\$ X 60.00
13	Rear fender side glass primer and cleaner	1	\$ 80.00	\$ X 80.00
14	Rear bumper clips	1	\$ 50.00	\$ X 50.00
15	Front & rear alloy rim RH	1	\$ 980.00	\$ <i>net</i> ✓ 980.00
16	Front & rear tyre RH	1	\$ 380.00	\$ X <i>n</i> 380.00
980 SPECIAL NETT TOTAL :				\$ 2,380.00

Nos.	LABOUR	S\$
1	R&R front door component	\$ 60 150.00
2	R&R rear door component	\$ 60 150.00
3	R&R rear side glass	\$ X <i>n</i> 250.00
4	R&R rear bumper reverse sensor	\$ 30 100.00
5	R&R front & rear undercarriage parts.	\$ 200 300.00
6	R&R front & rear tyre and balancing	\$ X 60. 100.00
7	Wheel alignment	\$ 80 ✓ 150.00
8	Diagnostic reset fault code	\$ X <i>n</i> 300.00
9	Conduct water leak test	\$ X <i>n</i> 120.00
10	Upholstery	\$ X <i>n</i> 300.00
11	Check wiring	\$ 30 100.00
12	Panel beating	\$ <i>700</i> 600 1,600.00
13	Rust proofing	\$ 30 200.00
14	Spray painting	\$ 1200 1,600.00
LABOUR TOTAL :		\$ 5,420.00

Tanphie 97495449

'WP' 12/5/21

L/S Resurvey after repair

Tanphie (Kuantan)
06 days

PARTS TOTAL : \$ 11,414.84
SPECIAL NETT TOTAL : \$ 2,380.00
LABOUR TOTAL : \$ 5,420.00
GRAND TOTAL : \$ 19,214.84

2465.55
980
2550

5995.55
L/S \$4750 #
06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: