	1		
(08/11/13) wef ASS. REC. BY: Marcus REF: CC6/C1	121005714/Ues3		
	GNMENT		
From: Date:	Veh No: SLV & Y6 / Yr Regn: 21/17/17 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /		
Estimated Cost:	Truck/Trailer or		
OD/ TP/ WS / TP RES / OD RES / EVA / INV / MV			
To Inspect Vehicle No:	Make: Peugeof 300f c.c //99 Colour A/C: Insured/Std/NI/NA		
at Workshop m/s ,	Mile		
of Insured: STA P7144			
	Eng/No: VF3MRHNYW, HC 20973)		
Policy No.	C/No: VF3MRHNYWHS 209732 Gen. Cond: Good / Fair / Poor / Burnt		
Claims No. Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or		
(Client's Record)	Brake: /norder / Jammed / Leaked / Burnt or		
Make of Veh:	Modi: Nil S/Rim / STD A/Rim or		
3	Tyre Size: F: 215/60217		
(Policy Condition)	R:		
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /		
repair at the time of inspection.			
Bal. or Market Value:	Front Continute		
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. 7 mm R/Bal. 7 mm		
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 7 mm L/Bal. 7 mm		
Est. Repairs:	D.O.A. 12(c/2/ D.O.L 11/s/2/		
Lum Sum: % 3 Val.: Yes or No	Survey held at		
03/26	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or		
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	Real		
Date: Person Contacted: Quality	The U/C / Chassis frame / Body Structure affected due to collision.		
Date / Time Action / Instruction have vides LTA & UST	2		
2/1/4 1/5 \$ 4000 Confined with Alan			
49/9/ 4/3 4 4000 CONT. MOR WIN The			
Date/Time, File Pass to? : Preli. Report	Days Of Repair:		
1) : Final Report	Resurvey No. of Trip: Survey Fee:		
Date/Time, File Return to?	Transportation:		
2) Add Fee	: Site Insp (\$)s+Rs,s		
	: Interview (\$) Photos		
Report Format :	: Tech. Invs (\$) Others		
Lump Sum / I.B.I: (\$:Weekend (\$		
	TOTAL		

alle Ashr

		The same
		Not Authorit
	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVE 6 #01-46,48,50 SINGAPORE 417883	11/5/1/ 1/5 \$ 4000
VEHICLE N	Io: SLV 846T	4 Lys
1PC	REAR BUMPER EXHAUST CHROMES @\$250.00 CALL REAR BUMPER REINFORCEMENT REAR BUMPER REINFORCEMENT BRACKETS @\$150.00 MARINE REAR BUMPER INNER RETAINER REAR BUMPER TOP SIDE COVERS @\$390.00 PARTINE REAR BUMPER TOP SIDE COVERS @\$390.00	\$2,155.00 \(\) \$105.00 \(\) \$102.00 \(\) \$420.00 \(\) \$388.00 \(\) \$399.00 \(\) \$399.00 \(\) \$52.00 \(\) \$52.00 \(\) \$650.00 \(\) \$500.00 \(\) \$300.00 \(\) \$370.00 \(\) \$780.00 \(\) \$780.00 \(\) \$780.00 \(\) \$1,205.00 \(\) \$288.00 \(\) \$1,210.00 \(\) \$14,058.00
1SET 1SET 1PC 1PC 1SET 1PC	S.NETT ITEM REAR BUMPER REVERSE SENSOR REAR BUMPER CLIPS REAR END PANEL SEALANT REAR WINDSCREEN SEALANT REAR REVERSE CAMERA REAR LICENCE PLATE W/HOLDER	\$280.00 X \$50.00 X \$50.00 X \$380.00 X \$50.00 X

TO CHECK MIDING	\$80.00
TO CHECK WIRING	11 \$80.00 ⊀
TO DISMANTLE & REPLACING REVERSE CAMERA	\$80.00 50
TO DISMANTLE & REPLACING REVERSE SENSOR	
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00 & 0
TO DISMANTLE & REFIX REAR WINDSCREEN	1√ \$150.00 ✓
TO TRANSFER TAILGATE MECHANISM	\$100.00 30
TO SPRAY RUST PROOFING	\$1,080.00
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,080.00 000

\$1,500.00 600 \$19,367.00

TOTAL

LKK Auto Consultants hence notify

To resurvey before/after spray painting

- To display damaged part(s) during resurvey

- Third party survey is on a "V/ithout Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

P-39V 102 P-3528.50 5.V-100.00 -- (380.00 50089