



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288X
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 38293

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

ATTN: AIG ASIA PACIFIC INSURANCE PTE LTD

DATE : 10/05/2021

CLAIM NO. : 11728

POLICY NO. : MC/00776833

FROM : HASRIANAH

VEHICLE NO. : FBR0027E

MAKE/MODEL : HON / CRF250L

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER FRONT MUFFLER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$149.00	149.00
2	COVER FRONT SIDE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$174.00	174.00
3	COVER FRONT UPPER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$138.00	138.00
4	COVER HEADLIGHT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$174.00	174.00
5	FASTENER, DUAL LOCK (11X28) P/N: 68727 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
6	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	5.00	\$63.00	315.00
7	MUDGUARD FRONT ASSY P/N: 68724 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$139.00	139.00
8	STAND SIDE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$133.00	133.00
9	STICKER COVER FRONT SIDE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$126.00	126.00

*38293 *

bizSAFE



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001: 2015

Quotation Nos. : 38293

(Page 2 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
10	STICKER COVER FRONT UPPER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$83.00	83.00 X
11	STICKER NO PLATE FRONT (SILVER) STRAIGHT P/N: 41354 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$24.00	24.00 lo
SUB TOTAL					\$1,486.00
GST @ 7 %					\$104.02
GRAND TOTAL (SGD)					\$1,590.02

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*38293 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001:2015