



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 492Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TORN	689.00	689.00
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	38.00	38.00
1	REAR KNUCKLER ARM RH	NOT NECESSARY	615.00	-
1	REAR KNUCKLER ARM BEARING WITH HUB RH	DAMAGED	288.00	288.00
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	389.00	-
1	REAR LOWER ARM RH	NOT NECESSARY	418.00	-
1	REAR TRAILING ARM RH	NOT NECESSARY	389.00	-
1	REAR FENDER INNER COWLING RH	NOT NECESSARY	212.00	-
1	REAR TAILLAMP RH	NOT NECESSARY	495.00	-
	LESS 20% DISCOUNT		-706.60	-203.00
			2,826.40	812.00
1	REAR SPORT RIM RH (SN)	CUT	1,221.00	500.00
	LESS 20% DISCOUNT		-244.20	-
			976.80	500.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR TYRE RH (SN)	NOT NECESSARY	190.00	-
1	REAR FENDER INNER COWLING CLIPS RH (SN)	NOT NECESSARY	80.00	-
1	REAR TAILLAMP CLIPS (SN)	NOT NECESSARY	6.50	-
			356.50	30.00
<u>LABOUR</u>				
	LABOUR FOR PANEL BEATING.		600.00	250.00
	LABOUR FOR SPRAYPAINTING.		600.00	400.00
	WIRING CHECK.		100.00	30.00
	TO APPLY TUFF COATING ON ACCIDENT AREAS.		200.00	30.00
	LABOUR FOR REMOVE & RENEW REAR UNDER CARRIAGE.		250.00	200.00
	TO CONDUCT ALIGNMENT.		150.00	80.00

Report Ref No. CS/UOI21005722/Atf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CONDUCT WATER CHECK LEAKAGE.	NOT NECESSARY	50.00	-
			1,950.00	990.00
GRAND TOTAL			6,109.70	2,332.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				2,332.00

Report Ref No. CS/UOI21005722/Atf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.