



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

11/05/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 07/05/2021

Estimated repair cost for vehicle no: SKU492Y MAZDA MAZDA3 4-DOOR SEDAN 1.5L

CHASSIS: JM6BM42A8G0310783 (2015)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>torn</i>	\$689.00	\$689.00 ✓
2	1	REAR BUMPER SIDE RETAINER RH <i>new</i>	\$38.00	\$38.00 ✓
3	1	REAR SPORT RIM RH <i>cut</i>	\$1,221.00	\$1,221.00 <i>504/501</i>
4	1	REAR KNUCKLER ARM RH <i>new</i>	\$615.00	\$615.00 +
5	1	REAR KNUCKLER ARM BREAIING WITH HUB RH <i>new</i>	\$288.00	\$288.00 ✓
6	1	REAR SHOCK ABSORBER RH <i>new</i>	\$389.00	\$389.00 +
7	1	REAR LOWER ARM RH <i>2 new</i>	\$418.00	\$418.00 +
8	1	REAR TRAILING ARM RH <i>new</i>	\$389.00	\$389.00 +
9	1	REAR FEDNER INNER COWLING RH <i>new</i>	\$212.00	\$212.00 +
10	1	REAR TAILLAMP RH <i>new</i>	\$495.00	\$495.00 +

1015
812

S.N. 500

TOTAL : \$4,754.00
LESS 20 % \$950.80
SUB-TOTAL : \$3,803.20

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 30
2	1	RERA TYRE RH <i>new</i>	\$190.00	\$190.00 +
3	1	REAR FENDER INNER COWLING CLIPS RH <i>new</i>	\$80.00	\$80.00 +
4	1	REAR TAILLAMP CLIPS <i>new</i>	\$6.50	\$6.50 +

30

TOTAL: \$356.50
TOTAL PARTS \$4,159.70

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING ON ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & RENEW REAR UNDER CARRIAGE
- 6 TO CONDUCT ALIGNMENT
- 7 TO CONDUCT WATER CHECK LEAKAGE

~~\$600.00~~ 250

~~\$600.00~~ 40

~~\$100.00~~ 30

~~\$200.00~~ 30

~~\$250.00~~ 200

~~\$150.00~~ 80

~~\$50.00~~ 10

Subtotal :- \$1,950.00

Total:- \$6,109.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adon L

L/s 12/05/21

04 Days.

total 2332

L/s 1.81k.