SPECIALISTS MOTOR PTE LTD

Block 3018A, 11hi Road J. #01-24-26. Singapore 408711 Tel 67472112 (5 lines) Fax 67438632

Finail- cardoc@singnet.com sg

Bus. Reg No. 199502604 F. GST No. 19-9502604-E.

L/S# 3800 S-days. Take the Afla repair

SM/SLC49631/2105042

11th May 2021

The Manager Motor Claim Department China Taiping Insurance (Singapore) Pte Ltd 3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Date of Accident

09th May 2021

Location

Yio Chu Kang Road

Third Party Claim Vehicle No :

SLC 4963 L Toyota Axio

Repair Cost For Vehicle No

GBE 950 H

Estimated Supply of Parts & Labours			Drice	An	ounts
1.50111		Qty	Price		787.50
No.		1	78 7.50	•	
1	Real book cover	1	50.70	\$	50.70 X
2	Rear boot emblem (logo)	2	59.40	-	ے دے 118.80
3	Rear boot hinge L&R W/S 1W/	1	194.20		194.20
4	Rear boot weather strip 701	1	129.20	\$	129.20
5	Rear fender inner garnish LH	1set	55.00	\$	55.00 ×
6	Rear fender inner garnish clips LH 11	1	339.60	\$	339.60
7	Rear lamp assy LH	1	696.30	\$	696.30
8	Rear end panel Bedy DO	1	230.60	\$ 2	230.60
9	Rear end panel inner garnish 70-1	1 set	55.00	\$	55.00 🗡
10	Rear end panel inner garnish clips 11	1	99.50	\$	99.50 🗶
11	Rear boot cover lock \$ \(\nu\)	1	50.30	\$	50.30 🔀
12	Rear boot cover latch 17	1		•	546.30
13	Rear bumper fascia DU	1	546.30	•	
	Rear bumper clips NU	lset	55.00	\$	55.00
14 15	Rear bumper side retainer L&R MSSerf Rear bumper bracket L&R MSS	2	100.40	\$ 2	ے مرا 200.80
	Real bulliper side retainer Elect	2	80.30	\$	160.60 17
16	Kear bumper bracket L&K / 1/2	-			380.00 200 S/N
17	Rear bumper sensor(s/nett)	1 set	380.00 _		
	(a com			\$ 4,	149.40

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711 Tel: 67472112 (5 lines) Fax: 67438032 Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SLC4963L/2105042

11th May 2021

<u>Labour Charges :-</u>	Amounts
Balance b/f	\$ 4,149.40
Cut out, renew, knocking & welding rear boot cover, rear fender LH, rear end panel, remove & install all damage parts, straighten rear chassis & re-align body	\$ 1,280.00 /000
Tuff-kote on damage parts	\$ 80.00 60
Spray painting on damage parts	\$ 1,500.00//00
Remove & refix rear bumper sensor	\$ 80.00 50
Check all lighting after repairs	\$ 45.00 20
Labour Charge	\$ 2,985.00
Total Amount	\$ 7,134.40

GST will be reflected in the final bills.

Notes: -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal medification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

co OneMotoring

Aire PARF/COE Rebate for Registered Vehicle Sehicle Owner Particulars

owner ID Type:

Owner ID:

Singapore NRIC

680D

Vehicle Details

Vehicle No.:

SLC4963L

Vehicle to be Exported:

No

Intended Deregistration Date:

27 May 2021

Vehicle Make:

TOYOTA

Vehicle Model:

COROLLA AXIO 1.5X A

Primary Colour:

White

Manufacturing Year:

2008

Engine No.: Chassis No.: 1NZD071988

Maximum Power Output:

NZE1416084263 81.0 kW (108 bhp)

Maximum Fower Outpo

\$13,766.00

Open Market Value:

12 Aug 2008

Original Registration Date: First Registration Date:

12 Aug 2008

Transfer Count:

4

Actual ARF Paid:

\$13,766.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

\$0.00

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

11 Aug 2023

COE Category:

A - Car (1600cc & below)

COE Period(Years):

5

PQP Paid:

\$17,099.00

COE Rebate Amount:

\$7,547.00

Total Rebate Amount:

\$7,547.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 May 2021





Accident Free Unit, Well Maintained Unit. \$3K Driveaway Available! Only At \$746 Monthly! Call/WhatsApp Our Sales Consultant Now To...

GS Automobiles Pte Ltd

Posted: 22-May-2021 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Corolla Axio 1.5A X

(COE till 09/2023)

\$17,800

\$7,800 /yr

08-Sep-2008

1,496 cc

Sedan

Available

Original Condition With No Wear And Tear To Replace, Accident-Free, Very Well Maintained Interior And Exterior, STA Evaluation For Pe...

Posted: 20-May-2021 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla



ompare

Toyota Corolla Axio 1.5A X (COE till 07/2023)

\$16,800 \$7,770 /yr 26-Jul-2008

1,496 cc

166,000 km

Sedan

Available

100% Loan Available! 2 Owners Only, Low Mileage Clocked, Affordable Budget And Depreciation, Fuel Saving! Well Maintained In Tip To...

Posted: 19-May-2021 Tags: 2008 Toyota Corolla, Toyota Corolla, Toyota, Corolla