

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims
Yr Ref: SML 3588 J

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0407/2021/JT

From
Telephone +65 -
Telefax +65 -
Email
Our Dept
Our Ref

08-SEP-2021 Date
1 Total Pages

Dear Sir,

RE: INSURANCE CLAIM FOR SML 3588 J - Audi Q8 3.0 TFSI QU

With reference to the above-mentioned vehicle, no. **SML 3588 J**, claimant, **Ms Nguyen Thi Thuy Hang**, please find the related document per attached.

1. A copy of the Original Invoice no. 85016679- S\$ 10,880.36
2. A copy of the Discharge Voucher duly signed by client.

Premium Automobiles Pte Ltd,
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Based on the above document, we would appreciate you could expedite the payment soonest possible.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG Insurance – SML 3588 J

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SML 3588 J

Norah Khai From
 6768 9911 Telephone +65 -
 6841 1183 Telefax +65 -
 Body Repair Our Dept

PA/OD/0407/2021/TF Our Ref
 4-Jun-2021 Date
 1 Total Pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q8 3.0 TFSI qu
Vehicle Chassis No. : WAUZZZF11KD015567
Vehicle Regn No. : **SML 3588 J**
Vehicle Mileage : 54,380 KM
Vehicle Owner : Ms. Nguyen Thi Thuy Hang
Certificate No : 1900114968-01
Own Damage Excess : S\$ 1,498.00 (Inclusive of 7% GST)
Accident Date : 6/5/2021
Place : 17 Toh Tuck Road Carpark
Repair Cost : S\$ 10880.36
WIP No. : 26515
Repairer’s Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd,
 Showroom
 9 Leng Kee Road
 Singapore 159090
 Telephone (65) 6566 1111
 Telefax (65) 6471 3733

Service & Parts Centres
 55 Ubi Rd 1
 Singapore 408699
 Telephone (65) 6336 2323
 Telefax (65) 684 11183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer’s charges that are claimable under the policy will be deemed in full and final settlement of property claim only.

Insured Signature : 
Time : 11am
Date : 10/6/21

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:47

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85016679 Date: 02/09/2021 Order: SML3588J Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SML3588J (V 40800) Regn Date: 28/06/2019 Mileage: 54380 WIP No.: 26515
Model: Q8 3.0 TFSI qu 4MN0X2 Chassis: WAUZZZF11KD015567 Engine: DCB 067483 Dept: U
You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1400.00	1.00	-1,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	600.00	1.00	600.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, REAR LID AND BOTH REAR WHEEL ARCH TRIMS.	2200.00	1.00	2,200.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
X	A4M8807067E GRU	009233/ (V) (GER) COVER	Less 020%	1.00	2669.00
X	A4M8807823A 9B9	(A) (SK) TRIM 17/5/21	Less 020%	1.00	85.80
X	A4M8807791A 1RR	(A) (SK) MOLDING 17/5/	Less 020%	1.00	423.00
X	A4M8807521C RU6	(A) (SK) SPOILER 17/5/	Less 020%	1.00	814.50
X	A4M8807319A	(A) (SK) PLATE AP 8/6/	Less 020%	1.00	94.80
X	A4M8945701A	(A) (SK) REFLECTOR 17/	Less 020%	1.00	135.50
X	A4M8945695B	TAIL LIGHT	Less 020%	1.00	3354.00
X	A4M8853742 2ZZ	AUDI SIGN	Less 020%	1.00	137.50
X	A4M8853741A 2ZZ	INSCRIPTION 'Q8'	Less 020%	1.00	98.80
X	A4G0853737 2ZZ	INSCRIPTION 'QUATTRO	Less 020%	1.00	98.80
X	A4M8853817A GRU	009233/ (V) (GER) COVER	Less 020%	1.00	376.50
X	A4M8853818A GRU	COVER (LAST)	Less 020%	1.00	376.50
X	A4M8807513A 1RR	(A) (SK) MOLDING 17/5/	Less 020%	1.00	244.00
X	A4M8807511 GRU	COVER EX	Less 020%	1.00	1362.00

Parts 8,216.56
Labour 0.00
Sublet 3,352.00
Menus 0.00
Lubricant 0.00

Sub-Total 10,168.56

7% GST 711.80

Grand Total 10,880.36



Received by

For & on behalf of
Premium Automobiles Pte Ltd