

威利摩哆

WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

AIG Asia Pacific Insurance PL

78 Shenton Way
#07-16
S 079120Attn Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SMR5642R

Accident involving vehicle no: SLF2539B/SMR5642R

DOA: 11/05/2021 AT Along Pasir Ris St 71

Dear officer incharge: 66 9830 • 079120

Estimate cost of repair for vehicle no: SLF2539B

To supply:

Description	Qty	Amount
Rear bumper	1	508.80
Rear bumper side	1	118.50
Rear fender	1	802.40
Taillamp	1	462.60
Arch garnish	1	96.00
Garnish clip		45.00
Parts		2,033.30
Parts less 20%		406.66
Claiming against your ins.		1,626.64
Accident involving vehicle		
DOA: 11/05/2021 AT Along Pasir Ris St 71		

To remove/reinstall triangle glass

To remove/reinstall rear seater, inner garnish enable repair job carry out

To remove damaged parts n attachments

Repair/reshape dented areas

To replace/align all parts into position

To spray paint

Rear fender

Taillamp

Arch garnish

Garnish clip

Parts

Parts less 20%

Claiming against your ins.

Accident involving vehicle

DOA: 11/05/2021 AT Along Pasir Ris St 71

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

120.00

180.00

Amount

850.00

600.00

802.40

3,376.64

96.00

45.00

2,033.30

406.66

1,626.64