



Claim	S1M03A1Q
Reference	CS4/ASM21005793/Ktce2
Loss Date	11 May 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Report Date	13 May 2021 2:32:32 PM
Request Date	14 May 2021
Due Date	
Services	Fire

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident

SMY4982D

Vehicle

Registration #

Make

BMW

Model

420 I

Service Address

51 Ubi Avenue 1 #01-25 Paya Ubi, , , 408933

Primary Contact/Insured

HARRISON DORILYN CIERVO

299 BEDOK SOUTH AVE 3, #01-06, 469298,

Singapore

97681627



Claim Handler

HO Winnie

winnie.ho@axa.com.sg

Additional Instructions FIRE - VEH AT K. KIM
HIN WORKSHOP

Messages2 Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2105112.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (OD)	23 July 2021
 Investigation Report-SMY4982D.pdf.pdf	Reports & Statement	Investigator / Adjustor Report	LKK AUTO CONSULTANTS PTE LTD (OD)	23 July 2021

FAQ English (SG) ▼ Elaine Kuan ▼			SUBTYPE	AUTHOR	DATE UPLOADED
 Service Requests Documents	...	im	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	27 May 2021
	 BWKA5536[1].MP4	Evidence	Videos	CHOW Soon Hee Gene	24 May 2021
	 SMY4982D photo.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	17 May 2021
	 Estimate SMY 4982 D.pdf.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	17 May 2021
	 AXA Immediate Advice _ SMY 4982D.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	17 May 2021
	 Estimate SMY 4982 D.pdf.pdf	Forms / Claim Documents	Assessment	K KIM HIN AUTO PTE LTD (VP)	15 May 2021
	 Driver IC & DL.pdf.pdf	Forms / Claim Documents	Driver's License / IDP	K KIM HIN AUTO PTE LTD (VP)	14 May 2021

