

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

Page 1/2

DATE: 14.05.2021MODEL: Hyundai IoniqINSURANCE: LONPACVEHICLE NO.: SHC2038TMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Boot Lid <i>305500</i>	1		\$2,480.40
	Emblem-Hybrid <i>NT</i>	1		\$24.30
	Emblem-Ioniq <i>NT</i>	1		\$31.30
	Antenna Assy-SMARTK <i>NT</i>	1		\$40.50
	Boot Lid Lamp(LH/RH) <i>0/5 one 1/5 on</i>	2	\$794.40	\$1,588.80
	Rear Bumper <i>DO/be</i>	1		\$459.40
	Rear Bumper Reinforcement <i>NT</i>	1		\$394.80
	Rear Bumper Reinforcement Bracket (LH/RH) <i>NT</i>	2	\$138.10	\$276.20
	Rear Bumper Centre Moulding Assy <i>cut</i>	1		\$451.25
	Rear Bumper Lower Centre Moulding Assy <i>NT</i>	1		\$155.00
	Rear Bumper Side Bracket (LH/RH) <i>NT</i>	2	\$55.80	\$111.60
	Rear Bumper Cover Clips <i>NT</i>	10	\$2.20	\$22.00
	Rear Bumper Under Centre Cover <i>NT</i>	1		\$225.00
	Rear Bumper Side Under(LH/RH) <i>NT</i>	2	\$108.00	\$216.00
	Rear Bumper Reflector Lamp(LH/RH) <i>NT</i>	2	\$41.45	\$82.90
	Rear Bumper Fog Lamp <i>NT</i>	1		\$201.50
	Rear Bumper Towing Cover <i>NT</i>	1		\$98.80
	Tail Lamp(LH/RH) <i>NT</i>	2	\$870.40	\$1,740.80
	Rear Spoiler <i>NT</i>	1		\$665.40
	Rear Bumper Fog Lamp <i>NT</i>	1		\$201.50
	Rear Lower Glass – Black <i>520</i>	1		\$584.90
	Rear Windscreen Moulding <i>NT</i>	1		\$48.50
	SUB TOTAL			\$10,100.85
	LESS 20%			\$2,020.17
	DISCOUNTED TOTAL			\$8,080.68
	Boot Lid ComfortDelGro <i>NT</i>	1		\$35.00
	Boot Lid 65521111 <i>NT</i>	1		\$35.00
	Boot Lid APPS <i>NT</i>	1		\$40.00
	Rear Bumper Reverse Sensor <i>shrub</i>	1		\$180.00
	Rear Bumper Rubber Mat <i>NT</i>	1		\$50.00
	Rear Windscreen Sealant <i>NT</i>	2	\$46.00	\$92.00
	Rear No.Plates W/Trim Cover <i>NT</i>	1		\$55.00
	BootLid Adv.Sticker <i>NT</i>	1		\$100.00
	Rear Bumper Adv.Sticker <i>NT</i>	1		\$50.00
	Rear Fender Adv.Sticker RH/LH <i>> complete</i>	2	\$100.00	\$200.00
	NETT TOTAL			\$837.00
	SPARE PARTS TOTAL			\$8,917.68

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
			SHC2038T	Page 2/2
	<u>Labour Charge</u>			
	Panel Beating 350		700	\$800.00
	Spray Painting Charge 250		750	\$900.00
	Wiring Charge		20	\$60.00
	Tuff Kote		30	\$80.00
	Remove/Refix Rear Windscreen Glasses		160	\$200.00
	Remove/Refix Reverse Sensor		40	\$120.00
	Diagnostic & Resetting To Erase Fault Code		120 MAX	\$300.00
	TOTAL LABOUR			\$2,460.00
	ESTIMATE TOTAL			\$11,377.68

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

p/p 6473.08
 Not Authorized
 LKH
 Marcus
 14/5/21
 Take photo before painting
 4 days
~~Marcus H. H. H.~~
 marcus@lkhauto.com.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5016.35
 202
 F- 4013.08
 S.V 760
 L- 1700
 6473.08

VEHICLE	: <u>SHC2038T</u>	TYPE OF CLAIM:	<u>TP</u>
MODEL	: <u>HYUNDAI IONIQ</u>	SURVEY BY	: <u>LKK-MARCUS</u>
JOB NO	: <u>305468560</u>	DATE	<u>14.05.21</u>

[illegible]

COMFORTDELGRO

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305468560
Date : 19/05/21

FINALIZATION FORM

To : LKK

Fax :

Attn : MARCUS CHUA

Vehicle Reg No. : SHC2038T

Date of Accident : 12/05/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: LONPAC --- GBE 580S

2. The finalized amount shall be:

(a) Spare Parts after List discount \$4,437.56

(b) Labour Charges \$2,080.00

Total for Part-By-Part Repair Cost

\$6,517.56

\$6473.08
CONFIRM

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 4 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : *LIM TS*

Signature : *MARCUS*

Name : LIM TS

Name : MARCUS

Tel : 62148398

Date : 19/5/21

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305468560
REGN NO : SHC2038T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.10.2018
DATE/TIME IN : 12.05.2021 13:35
ACCIDENT DATE : 12.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2256-G	BOOTLID	1	2,480.40	20.00	1,984.32
0002 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52
0003 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00
0004 04-01-0104-2257-G	BOOTLID LOWER GLASS	1	584.90	20.00	467.92
0005 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60
0006 28-01-0103-0005-A	BOOTLID COMFORTDELGRO	1	35.00		35.00
0007 28-01-0103-0006-A	BOOTLID 65521111	1	35.00		35.00
0008 28-01-9999-2025-A	BOOTLID APPS	1	40.00		40.00
0009 04-01-0104-1150-A	REAR BUMPER MAT	1	50.00		50.00
0010 09-01-9999-0068-A	REVERSE SENSOR	1	180.00		180.00
0011 FNPS	REAR NO.PLATE W/TRIM CVR	1 N	40.00		40.00
0012 04-01-0104-2398-G	BOOTLID LAMP RH	1	794.40	20.00	635.52
0013 04-01-0104-2380-G	<u>BOOTLID LATCH**</u>	1	224.00	20.00	179.20

4393-08
4986-38
501635

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305468560
REGN NO : SHC2038T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.10.2018
DATE/TIME IN : 12.05.2021 13:3
ACCIDENT DATE : 12.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0104-2270-G	BOOTLID EMBLEM-HYBRID	1	24.30	20.00	19.44	X Not Fitted
0015 04-01-0104-2271-G	BOOTLID EMBLEM-IONIQ	1	31.30	20.00	25.04	X

SUB-TOTAL : 4,437.56

JOB NATURE

0000 20-05	Rear Fender Adv.Sticker RH/LH	200.00
0001 PB	PANEL BEATING	700.00
0002 SP	SPRAYPAINT CHARGE	750.00
0003 17-01	CHECK ALL LIGHTING	20.00
0004 20-00	TUFF COAT ON AFFECTED PARTS.	30.00
0005 L	R/I REAR WINDSCREEN GLASSES	160.00
0006 L	R/I REVERSE SENSORS	40.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305468560
REGN NO : SHC2038T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.10.2018
DATE/TIME IN : 12.05.2021 13:3
ACCIDENT DATE : 12.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0007 20-05	REAR WINDSCREEN SEALANT	80.00
0008 20-05	BootLid Adv.Sticker	100.00

SUB-TOTAL : 2,080.00

TOTAL : 6,517.56

6473.08

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE
DATE :

Date/Time: 14.05.2021 10:16

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.:305468560

Customer: COMFORT TRANSPORTATION PTE LTD
Customer No: 7010045
Address: 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)


REGN NO.: SHC2038T	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 12.05.2021 13:35
YR OF MANU. 30.10.2018	TARGET DATE
CHASSIS CODE KMHC851CVKU115095	COMPLETION DATE/TIME:

Amount Card NO.

JOB DESCRIPTION

Accident Date: 12.05.2021
Nature: 3P 12.05.2021

/NO LABOR CODE DESCRIPTION



Worked & Passed Out By:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Delivery Slip

Exit Pass

No.: SHC2038T LIMITS

Vehicle No.: SHC2038T

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	821R

Vehicle Details

Vehicle No.:	SHC2038T
Vehicle to be Exported:	No
Intended Deregistration Date:	15 May 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4LEJU112150
Chassis No.:	KMHC851CVKU115095
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$24,855.00
Original Registration Date:	30 Oct 2018
First Registration Date:	30 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$11,797.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2026
PARF Rebate Amount:	\$8,847.00

Intended COE Rebate Details

COE Expiry Date:	29 Oct 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$24,228.00
COE Rebate Amount:	\$16,518.00
Total Rebate Amount:	\$25,365.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 May 2021

OK