

COMFORTDELGRO

REPAIR ESTIMATE*

VEHICLE NO SHC2532K

DATE 12/05/21 12:00 AM

MAKE :

MODEL PRIUS G4A

CHIANG/ AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR FENDER <i>Repair</i>			\$836.70 X
1	REAR FENDER SHIELD RH <i>u1</i>			\$134.20 X
1	REAR RH WHEEL CAP <i>cut</i>			\$177.70 ✓
1	REAR BUMPER COVER <i>re/cut</i>			\$458.60 ✓
1	REAR BUMPER SIDE BRACKET RH <i>su</i>			\$94.80 X
	SUB TOTAL			\$1,702.00
	LESS 25%			\$425.50
	DISCOUNTED TOTAL			\$1,276.50
	REAR DOOR COMFORT APP LOGO <i>u1</i>			\$80.00 X
				\$80.00
	Labour Charge			
	Panel Beating <i>350</i>		<i>700</i>	\$1,050.00
	Spray Painting Charge		<i>500</i>	\$600.00
	Remove and Refix upholstery		<i>60</i>	\$90.00
	Check Wiring		<i>20</i>	\$60.00
	tuff coat		<i>u1</i>	\$80.00 X
	TOTAL LABOUR			\$1,880.00
	ESTIMATE TOTAL			\$3,236.50

LKK Auto Consultant's hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Not Authorized
Lkk meras
14/5/21 @ 11am.

Take photo before painting
3 days.

mercuschua@lkkauto.com

P- 636.30

25%

477.22

1157.22

Our Job Ref No : 305468495
Date : 18/05/21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : MARCUS

Vehicle Reg No. : SHC2531K

11/05/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2 The repair job shall bill to: AIG SGP8889H

2. The finalized amount shall be:

(a) Spare Parts after List discount \$477.22

(b) Labour Charges \$1,280.00

Total for Part-By-Part Repair Cost \$1,757.22

(c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: _____
Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : _____

Signature : _____

Name : CHIANG

Name : _____

Tel : 62148314

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 18.05.2021

Time: 13:17:49

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305468495
REGN NO : SHC2531K
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 05.12.2019
DATE/TIME IN : 12.05.2021 10:05
ACCIDENT DATE : 11.05.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2712-G COVER REAR BUMPER 1 458.60 25.00 343.95

0002 03-01-0302-2137-G CAP WHEEL 1 177.70 25.00 133.27

SUB-TOTAL : 477.22

JOB NATURE

0000 PB PANEL BEATING 700.00

0001 SP SPRAYPAINT CHARGE 500.00

0002 20-204 REMOVE/REFIX UPHOLSTERY ASST REPAIR 60.00

0003 17-01 CHECK ALL LIGHTING 20.00

SUB-TOTAL : 1,280.00

TOTAL : 1,757.22 ✓

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :