



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9887 4031
Email: yeeautopte ltd@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S: LONPAC INSURANCE BHD
300, BEACH ROAD
#17-04/07, THE CONCOURSE
SINGAPORE 199555

Estimate No: ES2100048
Date: 14 May 2021

Policy No:
Veh Reg No: GBA5469U
Make/Model: TOYOTA HIACE AUTO
Chassis No: JTFHS02P800020821
Engine No: 2KD1302609
Reg. Date: 31/10/2005

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 05/05/2021
TP Veh Reg No: GBC5253P

Not Authorize
61 Imp 820501
Presumy After Paint
3 days

Estimate Repair Cost to Vehicle No :GBA5469U

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 BODY STICKER - RH	400.00	1 PC	400.00	180.00
2 WHEEL RIM HUP CAP - RH	180.00	1 PC	180.00	180.00
			580.00	580.00
Spare Parts				
3 REAR BODY PANEL - RH	2,585.50	1 PC	2,585.50	2,585.50
4 REAR BUMPER SIDE RETAINER - LH	64.50	1 PC	64.50	64.50
5 REAR BUMPER SIDE RETAINER - RH	64.50	1 PC	64.50	64.50
			2,714.50	2,714.50
Labour				
TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,600.00	1 JOB	1,600.00	1,600.00
TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,600.00	1 JOB	1,600.00	1,600.00
TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	120.00	120.00
TO REMOVE/REFIT PASSENGER SEAT TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	200.00
TO CHECK WIRING FUNCTIONS.	50.00	1 JOB	50.00	50.00
WHEEL ALIGNMENT	120.00	1 T	120.00	120.00
			3,690.00	3,690.00
			Total	SS 6,984.50
			Add GST @ 7%	488.92
			Total Amount Payable	SS 7,473.42

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED SEVENTY THREE AND CENTS FORTY TWO ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Yee Auto Pte Ltd



AUTHORISED SIGNATURE