



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21005817/Atf3n2 Date: 08/10/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMC 3486S	Veh. Inspected	SLL 9212R	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10010242/ST	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	14/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI SX4	c.c	1586	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JSAGYA21S00203748	Colour	BLUE	
Odometer	155745 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/05/2021	Inspection Date	25/05/2021	
Survey held at	ADVANCE AUTO GARAGE 10 KAKI BUKIT ROAD 2 #03-01 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		