



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21005864/Uuf3n2	
			Date: 04/06/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKA 7691Z	Veh. Inspected	SLQ 3381Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2101370/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	17/05/2021	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi LANCER (A)	c.c	1590	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JMYSRCY1AGU006659	Colour	BLACK	
Odometer	97738 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CONTINENTAL	7 mm	
L/H Front Tyre	205/60 R16	CONTINENTAL	7 mm	
R/H Rear Tyre	205/60 R16	CONTINENTAL	7 mm	
L/H Rear Tyre	205/60 R16	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/04/2021	Inspection Date	18/05/2021	
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	