



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHU Xichi Eugene			Ref: CC4/ASM21005865/Upa3q2 Date: 07/06/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGT 3983E	Veh. Inspected	FBR 2289C
	Policy No.	GA569079/1	Coverage (\$)	0.00
	Claim No.	S1M03A55	Excess (\$)	0.00
	Assign From		Assign Date	17/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA T150	c.c	150
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	MH3UG131000001562	Colour	GREY
	Odometer	15908 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	90/80-17	IRC	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	120/70-17	IRC	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/05/2021	Inspection Date	18/05/2021
	Survey held at	HL CYCLE PL 1 KAKI BUKIT AVE 6 #02-58 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	