

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 15.05.21 (Saturday)

(LUMP SUM)

INSURANCE: AIG ASIA

MODEL: Hyundai i40

MVA: LIMITS

VEHICLE NO.: SHC7197J CityCab

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper Cover <i>CPH</i>	1		\$1,052.20
	Front Bumper Grille (RH) <i>x NN</i>	1		\$187.20
	Front Bumper Bracket Top (RH) <i>?</i>	1		\$22.40
	Front Bumper Bracket (RH) <i>CPA</i>	1		\$24.60
	Headlamp (RH) <i>scr</i>	1		\$1,800.00
	Front Fender (RH) <i>truc</i>	1		\$663.00
	Front Fender Shield (RH) <i>RL</i>	1		\$174.90
	Front Wheel Cap RH <i>cut</i>	1		\$217.20
	SUB TOTAL			\$4,141.50
	LESS 20%			\$828.30
	DISCOUNTED TOTAL			\$3,313.20
	Labour Charge			
	Panel Beating			\$600.00
	Spray Painting Charge			\$600.00
	Wiring Charge			\$40.00
	Tuff Kote			\$40.00
	Towing Fee			\$60.00
	TOTAL LABOUR			\$1,340.00
	ESTIMATE TOTAL			\$4,653.20

560
500
120
11

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

4 Days.
4S
A few part photos.
base air
17/5/21
3pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: