



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 9243T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,000.00	562.00
1	FRONT BUMPER RETAINER (CONSISTENT)	DEFORMED	400.00	45.00
1	LEFT HAND FRONT HEADLAMP (CONSISTENT)	CRACKED	800.00	430.00
1	LEFT HAND FRONT SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	500.00	-
1	LEFT HAND FRONT HEADLAMP PANEL (CONSISTENT)	NOT NECESSARY	500.00	-
1	LEFT HAND FRONT FENDER (CONSISTENT)	BENT	800.00	391.00
1	LEFT HAND FRONT FENDER INNER PANEL (CONSISTENT)	NOT NECESSARY	500.00	-
1	LEFT HAND FRONT SIDE FENDER BRACKET (CONSISTENT)	NOT NECESSARY	300.00	-
1	LEFT HAND FRONT FENDER SHIELD (CONSISTENT)	TORN	500.00	145.00
1	LEFT HAND FRONT DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,000.00	-
	LESS 20% DISCOUNT		-	-314.60
			6,300.00	1,258.40
<u>SPECIAL NETT ITEMS</u>				
1	LEFT HAND FRONT BUMPER CLIP (SN)(CONSISTENT)	NECESSARY	150.00	30.00
1	FRONT FENDER SHIELD CLIP (SN)(CONSISTENT)	NECESSARY	150.00	20.00
			300.00	50.00
<u>LABOUR</u>				
	CHECKING OF WIRING ,LIGHTING AND RESETTING.		100.00	30.00
	WHEEL ALIGNMENT.		100.00	80.00
	WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS ,REPAIRS INCLUDING CUT AND WIELD ,REALIGN BODY STRUCTURE.INCLUSIVE OF THE REPAIR OF LEFT HAND FRONT DOOR.		1,200.00	500.00
	RESPRAY INCLUDING POLISHING AND WAXING ON THE CHARGES BODY PARTS ,REPAIRED PORTORTION WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	600.00
			2,400.00	1,210.00
GRAND TOTAL			9,000.00	2,518.40



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	-----------------

Report Ref No. CC4/ASM21005890/T1gs3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.