



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

| Account Details   | Account No.                 | Customer Details                             |
|-------------------|-----------------------------|----------------------------------------------|
| THIRD PARTY CLAIM | S1000020 / TPCLAIM          | M/S Grab Rentals Pte Ltd                     |
|                   | Document No.<br>0           | 6 Battery Road<br>#38-04<br>Singapore 049909 |
|                   | Document Date<br>17/05/2021 | Work: 65703925                               |

| Year              | Model      | Variant   | Reg. Date        | Reg. No.   | Kilometers   | Wip No.    | Order No. / Remarks |
|-------------------|------------|-----------|------------------|------------|--------------|------------|---------------------|
| 2018              | ZVW40R     | AWXEBW Q2 | 20/06/2018       | SMA7868H   | 0            | 62125      | 69DS/SMA7868H       |
| Chassis No.       | Engine No. | Terms     | SA / Counter     | Vehicle In | Collected On |            |                     |
| JTDZS3EU40J028196 | 2ZR0B85897 | 60        | Raymond Seah L M | --/--/---- | 0.00         | --/--/---- | 0.00                |

| L | Cd | Job/Parts Description                                                                                                                                                                    | Qty  | Unit Price | Disc % | Amount  |
|---|----|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------|--------|---------|
| 1 | Z  | BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR<br>TP VEH :SHC4788A ACC DATE:14/05/2021<br>TP INS: NO OF REPAIR DAYS:<br>DATE-IN: DATE SURVEY:<br>BY: AUTHORISED ON:<br>-TP/DS CLAIM |      |            |        | 30.00   |
| 2 | B  | BP-ECU2 TO RESET ECU AND REPROGRAMME                                                                                                                                                     |      |            |        |         |
| 3 | B  | BP-LAB2 TO CHECK WIRING AND LIGHTING.                                                                                                                                                    |      |            |        | 122.40  |
| 4 | B  | BP-MECH2 TO CONDUCT WHEEL ALIGNMENT CHECK.                                                                                                                                               |      |            |        | 180.00  |
| 5 | B  | BP-LAB2 TO REPLACE/REPAIR FRONT RH SIDE<br>ACCIDENT DAMAGE PARTS.                                                                                                                        |      |            |        | 2880.00 |
| 6 | B  | BP-RES2 TO SPRAY PAINT ON FRONT RH SIDE<br>ACCIDENT AFFECTED AREAS.                                                                                                                      |      |            |        | 2950.00 |
| 7 | 1  | U53801-47100 FENDER SUB-ASSY, FR                                                                                                                                                         | 1.00 | 850.30     |        | 850.30  |
| 8 | 2  | U53875-47061 LINER, FR FENDER, RH                                                                                                                                                        | 1.00 | 172.70     |        | 172.70  |
| 9 | 3  | U75374-47112 EMBLEM, SIDE PANEL                                                                                                                                                          | 1.00 | 54.60      |        | 54.60   |

| For & on behalf of                | Customer's Signature                  | Charge Summary         | Total               |
|-----------------------------------|---------------------------------------|------------------------|---------------------|
| Borneo Motors (Singapore) Pte Ltd |                                       |                        | 7,240.00            |
|                                   | Please acknowledge receipt of vehicle | Parts 1,077.60         | GST 7.00% 506.80    |
|                                   |                                       | Labour 6,162.40        |                     |
|                                   |                                       | Sublet 0.00            | Less 0.00           |
|                                   |                                       | Lubrication/Fluid 0.00 |                     |
|                                   |                                       | Others 0.00            | Amount Due 7,746.80 |

Company Copy