

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg

GST 201119451E RCB NO.201119451E

not Authorized
18/5/21
1/58
telephone # for
regi
15 days.

M/S : MS FIRST Capital Insurance Limited
36 Robinson Road #16-01
CITY HOUSE
Singapore 068877

TEL: FAX:
ATTN: Motor Claim Department
Your Ref No : 21/FC/TP-087(05)
Claim Type : Third Party
Accident Date : 14/05/2021
TP Veh Reg No : SHD6334G

Claim No :
No :
Date : 15/05/2021
Policy No : GA571416
Veh Reg No : SMY1281M
Make / Model : AUDI A4
Chassis No : 0
Engine No :
Reg. No :

ESTIMATE FOR VEHICLE NO: SMY1281M

Discription	Quantity	List Price	Amount
Cost Price		S\$	S\$
1 FRT BONNET	1 PC	3uc \$1,292.10	✓
2 FRT GRILLE ASSY	1 PC	one \$551.50	✓
3 FRT BUMPER	1 PC	one \$1,805.70	✓
4 FRT BUMPER RETAINER LH	1 PC	one \$71.70	✓
5 FRT BUMPER CLIPS	10 PCS	one \$10.00	✓
6 FRT BUMPER FOG LAMP LH	1 PC	one \$218.50	✓
7 FRT BUMPER FOG LAMP GARNISH LH	1 PC	one \$142.50	✓
8 FRT BUMPER FOG LAMP CHROME LH	1 PC	one \$123.50	✓
9 FRT BUMPER INNER SPONGE	1 PC	one \$570.00	✓
10 FRT BUMPER REINFORCEMENT	1 PC	one \$1,615.40	✓
11 LH HEADLAMP	1 PC	one \$931.00	✓
12 HEADLAMP SUPPORT PANEL	1 PC	one \$218.90	✓
13 LH HEADLAMP NOOZLE	1 PC	one \$123.90	✓
14 LH HEADLAMP NOOZLE COVER	1 PC	one \$111.70	✓
15 LH HEADLAMP NOOZLE COVER BASE	1 PC	one \$124.00	✓
16 NOOZLE HOSE	1 PC	one \$124.00	✓
17 LH HEADLAMP LOWER BRACKET OUTER	1 PC	one \$741.20	✓
18 LH HEADLAMP LOWER BRACKET INNER	1 PC	one \$608.90	✓
19 AIRCON CONDENSER	1 PC	one \$601.70	✓
20 RADIATOR	1 PC	one \$218.50	✓
21 ININTERCOOLER	1 PC	one \$503.50	✓
22 LH INTERCOOLER HOSE	1 PC	one \$684.10	✓
23 AIRCON LIQUID PIPE	1 PC	one \$165.70	✓
24 AIRCON DISCHARGE PIPE	1 PC	one \$165.70	✓
25 HEADLAMP SUPPORT TOP GARNISH	1 PC	one \$191.70	✓
26 POWER STEERING FLUID TANK	1 PC	one \$744.10	✓
27 RADIATOR HOSE LH	1 PC	one \$211.90	✓
28 FRT LH FENDER	1 PC	one \$100.00	✓
29 FRT LH FENDER INNER COWLING	1 PC	one \$161.70	✓
30 INNER COWLING CLIPS	10 PCS	one \$731.60	✓
31 FRT LH FENDER INNER COWLING FRT JOINT	1 PC	one \$418.60	✓
32 LH HEADLAMP HID UNIT	1 PC	one \$61.90	✓
33 LH HEADLAMP BULB	1 PC	one \$2,851.20	✓
34 FRT LH FENDER " S-LINE" PLATE	1 PC	one \$72.50	✓
35 FRT SHOCK ABSORBER	2 PCS	one \$560.70	✓
36 FRT LH SHOCK ABSORBER STOPPER	1 PC	one \$978.60	✓
37 FRT LOWER ARM	2 PCS	one \$807.60	✓
38 FRT TRAILING ARM	2 PCS	one \$1,121.40	✓
39 FRT KNUCKLE ARM	2 PCS	one \$1,957.20	✓
			one \$1,615.20

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg

GST.201119451E RCB NO.201119451E

M/S : MS FIRST Capital Insurance Limited
36 Robinson Road #16-01
CITY HOUSE
Singapore 068877

TEL: FAX:
ATTN: Motor Claim Department
Your Ref No : 21/FC/TP-087(05)
Claim Type : Third Party
Accident Date : 14/05/2021
TP Veh Reg No : SHD6334G

Claim No :
No : EST21051502
Date : 15/05/2021
Policy No : GA571416
Veh Reg No : SMY1281M
Make / Model : AUDI A4
Chasis No : 0
Engine No :
Reg. No :

ESTIMATE FOR VEHICLE NO: SMY1281M

Discription	Quantity	List Price	Amount	
			S\$	S\$
40 FRT KNUCKLE BEARING	2 PCS	\$532.00	\$1,064.00	?
41 FRT UPPER ARM	2 PCS	\$494.00	\$988.00	?
42 FRT ANTI ROLL BAR LINK	2 PCS	\$119.70	\$239.40	?
43 STEERING CROSSMEMBER	1 PC		\$4,180.00	?
44 STEERING RACK ASSY	1 PC		\$5,510.00	?
45 FRT LH DRIVE SHAFT	1 PC		\$2,755.00	x
46 ROCKER PANEL	2 PCS	\$1,850.00	\$3,700.00	—
47 ROCKER PANEL OUTER GARNISH	2 PCS	\$881.70	\$1,763.40	—
48 FRT BUMPER UNDER COVER	1 PC		\$218.70	?
49 ENGINE UNDER COVER	1 PC		\$491.70	?
50 ENGINE UNDER COVER CLIPS	6 PCS	\$10.00	\$60.00	—
51 BODY UNDER COVER	2 PCS	\$441.70	\$883.40	—
52 BODY UNDER COVER CLIPS	18 PCS	\$10.00	\$180.00	—
53 LH EXHAUST BOX	1 PC		\$1,100.00	x
54 LH EXHAUST BOX RUBBER HOLDER	2 PCS	\$95.00	\$190.00	x
55 LH EXHAUST BOX HEAT SHIELD	1 PC		\$299.70	x
56 FLOOR PANEL UNDER COVER	1 PC		\$1,650.90	?
57 REAR SHOCK ABSORBER	2 PCS	\$1,102.50	\$2,205.00	?
58 REAR LOWER ARM	2 PCS			?
59 REAR KNUCKLE ARM	2 PCS	\$1,187.50	\$2,375.00	?
60 REAR KNUCKLE BEARING	2 PCS	\$560.70	\$1,121.40	?
61 REAR UPPER ARM	2 PCS	\$495.60	\$991.20	?
62 REAR TRAILING ARM	2 PCS	\$777.50	\$1,555.00	?
63 REAR STAY ARM	2 PCS	\$222.70	\$445.40	?
64 REAR CROSSMEMBER	1 PC		\$4,750.00	?
65 REAR RH DOOR	1 PC		\$2,900.90	—
66 FRT RH DOOR	1 PC		\$1,911.50	—
67 REAR RH FENDER	1 PC		\$3,040.70	x
68 REAR WINDSCREEN MOULDING	1 PC			x
			\$68,623.00	
Less 10%			\$6,862.30	
			\$61,760.70	

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg

GST:201119451E RCB NO:201119451E

M/S : MS FIRST Capital Insurance Limited
36 Robinson Road #16-01
CITY HOUSE
Singapore 068877

TEL: FAX:
ATTN: Motor Claim Department
Your Ref No : 21/FC/TP-087(05)
Claim Type : Third Party
Accident Date : 14/05/2021
TP Veh Reg No : SHD6334G

Claim No :
No : EST21051502
Date : 15/05/2021
Policy No : GA571416
Veh Reg No : SMY1281M
Make / Model : AUDI A4
Chasis No : 0
Engine No :
Reg. No :

ESTIMATE FOR VEHICLE NO: SMY1281M

Discription	Quantity	List Price	Amount
		S\$	S\$
SPECIAL NET:			1600
1 SPORT RIM	4 PCS	\$550.00	\$2,200.00
2 TYRE	4 PCS	\$280.00	\$1,120.00
3 RADIATOR COOLANT	1 PC		\$25.00
4 REAR WINDSCREEN GUM	1 PC		\$60.00
TOTAL			\$3,405.00

Labour			
1 WIRE CHECKING	30	\$50.00	?
2 REMOVE & REFIX AIRCON AND GAS		\$100.00	
3 REMOVE & REFIX FRT UNDERCARRIAGE (WITH CROSSMEMBER AND RACK)	350	\$400.00	
4 REMOVE & REFIX REAR UNDER CARRIAGE (WITH CROSSMEMBER)	300	\$400.00	
5 4 WHEEL ALIGNMENT		\$100.00	✓
6 REMOVE & REFIX CUSHION AND SEATS	80	\$220.00	
7 TOWING FEE (KING ROLLER)	3.11	\$500.00	?
8 TRANSFER DOOR COMPONENT FROM OLD TO NEW		\$120.00	✓
9 LABOUR CHARGE	2000	\$2,800.00	
10 SPRAY PAINTING	2000	\$2,400.00	
TOTAL			\$7,090.00

Amount Before Excess	\$72,255.70
Add GST @7%	\$5,057.90
Total Amount Payable	\$77,313.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For SME MOTOR PTE LTD

AUTHORISED SIGNATURE