

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	26 Mar 2021 19:37	Clm Veh Model Changed		[] Merimen Administrator
2	26 Mar 2021 19:37	Clm Created	Reg No: SMN5695J. Policy No: 999995580. Acct Date: 2021/03/26. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SA0A213Q0007	[I] Merimen Administrator
3	01 Apr 2021 16:33	Clm Registration Modified	Acct Time:10:21:00->10:00:00. Pol No:999995580->0999993662.	[I] Low, Xianyu
4	01 Apr 2021 16:40	Clm Registration Modified	Init.Est.->5,000 - 6,000.	[I] Low, Xianyu
5	18 May 2021 11:25	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
6	18 May 2021 11:25	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
7	18 May 2021 11:25	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
8	18 May 2021 11:25	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/05/28	[A] LEE SU THING
9	18 May 2021 11:25	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] LEE SU THING
10	18 May 2021 11:25	Clm Registration Modified	Rep:1137->200237.	[A] LEE SU THING
11	18 May 2021 11:25	Clm Veh Model Changed	(206854) MERCEDES-BENZ C180 1.5 COUPE (R17 LED) (A).	[A] LEE SU THING
12	18 May 2021 11:26	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] LEE SU THING
13	18 May 2021 14:21	Adj Rpt Initiated		[A] HUEY YON
14	18 May 2021 14:21	Insured Phone No Updated	[6591876216] -> [+656591876216]	[A] HUEY YON
15	18 May 2021 14:21	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
16	18 May 2021 14:21	Clm Dtl Modified	JPJ Reg. Date: -> 2019/08/19.	[A] HUEY YON
17	18 May 2021 14:21	Clm Details Notified		[A] HUEY YON
18	18 May 2021 14:25	Clm Veh Model Changed	(206854) -> (205121) MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A).	[] Merimen Administrator
19	18 May 2021 15:58	Clm Registration Modified	Excess: -> 5200.00. 2F Remarks: -> Inexperience Driver. GST: -> 7.00.	[I] Mithoo Singh, Aashweenjeet Kaur
20	18 May 2021 15:58	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
21	19 May 2021 10:11	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/05/28	[A] SHIAU CHAN
22	19 May 2021 10:12	Adj Mandate Request	Cur.Req:4869.85:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] SHIAU CHAN
23	19 May 2021 11:51	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/05/28. Mandate Remarks: Vehicle may commence repair. (Front Bumper to repair) Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels a	[I] Lim, Kok-Chong
24	19 May 2021 11:51	Adj Mandate Set	Approved:2997.55:Vehicle may commence repair. (Front Bumper to repair) Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair.	[I] Lim, Kok-Chong

Date From    Date To    Audit Type 

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2695210	18 May 2021 14:21:10	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SMN5695J		11.00