



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 26/03/2021

ESTIMATE

NO : QUOT202104-000009(00)

DATE : 18/05/2021

POLICY NO : 999995580

VEH REG NO : SMN5695J

MAKE/MODEL : MERCEDES BENZ C180 AVG
(R17 LED)

CHASSIS NO : WDD2050402R510526

ENGINE NO : 27491031804489

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : SMN5695J

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy - RH	1	1,850.00	1,850.00
2 Front bumper	1	1,080.00	1,080.00
3 Front bumper reinforcement	1	310.00	310.00
4 Front bumper side retainer - RH	1	38.00	38.00
5 Front bumper sensor	1	138.00	138.00
6 Front bumper sensor seals	6	8.00	48.00
7 Front bumper lower chrome	1	165.00	165.00
8 Front bumper clips	15	5.50	82.50
Headlamp lower bracket - RH			3,711.50
		Add 10%	371.15
			4,082.65
LABOUR			
9 To remove and refit front bumper sensor	1	100.00	100.00
10 To check and rectify wiring system	1	80.00	80.00
11 To panel beat and straighten RH front fender, LH front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
12 To putty and spray paint on affected areas	1	800.00	800.00
13 To reset and reprogramme headlamp fault code	1	350.00	350.00
			2,330.00
		TOTAL	S\$ 6,412.65
		ADD GST @ 7%	448.89
		GRAND TOTAL	S\$ 6,861.54

SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED SIXTY-ONE AND CENTS FIFTY-FOUR ONLY

\$ 4,572.40
 XS 1,700.00
 \$ 2,872.40
 7% 201.06
 \$ 3,073.46

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

TAX INVOICE

8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0853
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

GST REG.NO.: M2-0090482-6 CO REG.NO.: 198905613E

ACCOUNT NUMBER : TONGLUC1 TIME:10:40
TONG LUCK AUTO PTE LTD
160,SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722
575722
Telephone No: 62500088

ROUTE
SML

DELIVER TO :

TONG LUCK AUTO PTE LTD
160,SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

INVOICE NO. 8219764

DATE	20/05/2021	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	SMIN5695J	OUR REF.	19011

PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA205 820 05 61	HEADLAMP UNIT	6B-3B	1 PC	1,850.00	1,850.00
2 MBA205 880 01 40 9999	TRIM BUMPER	4B-1AA	1 PC	1,080.00	1,080.00
3 MBA205 620 34 01	BRACKET	1E-7C	1 PC	68.00	68.00
4 MBA000 905 55 04	DISTANCE SENSOR	1E-9C	1 PC	138.00	138.00
5 MBA000 542 12 51	DECOUPLING RING	1A-01F	6 PCS	8.00	48.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVAILING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE.

Exclusive Distributor



Stockists

SIGN & COMPANY'S STAMP

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 016
Account No.: 503-309-511-3
*Please send a screen shot of your payment/transfer confirmation to
account@minghee.com

TOTAL	SIN	3,184.00
ADD GST	7%	222.88
AMOUNT DUE	SIN	3,406.88



DATE
ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.