

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Like HSA 709
Not Authored
18/5/21
2/s & 13,000
6 days.

VEHICLE No: SLS 4260Y

1PC	FRONT DOOR N/S	Bolt	2025.20	\$3,250.00	—
1PC	FRONT DOOR GLASS OUTER MOULDING N/S	nee	215.35	\$315.00	—
1PC	FRONT DOOR GLASS FRAME GARNISH N/S	nee	88.00	\$118.00	—
1PC	FRONT DOOR GLASS REGULATOR & MOTOR N/S	Bolt/nee	485.20	\$945.15	—
1PC	FRONT DOOR INNER LOCK N/S	shorted	197	\$655.22	—
1PC	FRONT DOOR INNER TRIM BOARD N/S	de/cne	1949.70	\$1,988.20	—
1SET	FRONT DOOR INNER TRIM BOARD CLIPS N/S	nee		\$60.00	—
1PC	FRONT DOOR INNER RUBBER N/S	nee	188.00	\$329.00	—
1PC	FRONT DOOR FRAME TOP CHROME MOULDING N/S	nee	325.00	\$482.00	—
1PC	FRONT DOOR CHANNEL N/S	11		\$455.10	X
1PC	REAR DOOR N/S	DD/Bolt	2015.20	\$3,100.00	—
1PC	REAR DOOR GLASS OUTER MOULDING N/S	nee	210.30	\$315.00	—
1PC	REAR DOOR GLASS FRAME GARNISH N/S	nee	88.00	\$118.00	—
1PC	REAR DOOR INNER LOCK N/S	see		\$655.22	X
1PC	REAR DOOR INNER TRIM BOARD N/S	de/cne	1922.30	\$1,955.20	—
1SET	REAR DOOR INNER TRIM BOARD CLIPS N/S	nee		\$60.00	—
1PC	REAR DOOR INNER RUBBER N/S	nee	188.00	\$322.90	—
1PC	REAR DOOR FRAME TOP CHROME MOULDING N/S	nee	315	\$455.00	—
1PC	REAR DOOR CHANNEL N/S	11		\$420.00	X
1PC	REAR FENDER N/S	Bolt/wheel	1766.20	\$2,480.00	—
1PC	REAR WINDSCREEN MOULDING	11		\$181.00	X
1PC	REAR WINDSCREEN SEALANT	11		\$50.00	X
1PC	REAR BUMPER	de/Yorn	1579.85	\$2,150.00	—
1PC	REAR BUMPER SIDE HOLDER N/S	11		\$116.00	X
1SET	REAR BUMPER CLIPS	11		\$60.00	—
1PC	ROCKER PANEL GARNISH N/S	de/Yorn	915.20	\$988.10	—
1PC	REAR SHOCK ABSORBER N/S	11		\$358.00	X
1PC	REAR WHEEL HUB N/S	11		\$850.00	X
1PC	REAR WHEEL HUB BEARING N/S	11		\$450.00	X
1PC	REAR SPORT RIM '20 INCH'	2		\$1,800.00	X
				\$25,482.09	

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	11	\$150.00 X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$150.00 80
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	11	\$200.00 X
TO CONDUCT WHEEL ALIGNMENT		\$120.00 60
TO TRANSFER BOTH DOOR MECHANISM		\$180.00 140
TO RESET & REPROGRAMME SYSTEM		\$200.00 80
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$1,200.00 800
TO PUTTY & SPRAY PAINTING		\$1,800.00 1100
TOTAL	\$29,612.09	

15/101.72

52
14346.63

16676.63