

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887
Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SJE8695Y
 Date: 28.5.21 14:13

Factory Japan 2019.0.1 Copyright (c) 2018 Hunter Engineering : Honda : Stream : RN6

Front : Left

Actual	Before	Specified Range
-0°38'	-0°36'	-0°45' 0°45'
3°04'	3°04'	3°15' 5°15'
-0°11'	-0°07'	-0°05' 0°05'
12°45'	12°45'	9°55' 11°55'
12°09'	12°09'	9°10' 12°40'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°49'	-0°49'	-0°45' 0°45'
2°42'	2°42'	3°15' 5°15'
-0°10'	-0°13'	-0°05' 0°05'
13°11'	13°11'	9°55' 11°55'
12°22'	12°22'	9°10' 12°40'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°13'	0°13'	-0°45' 0°45'
0°21'	0°21'	
-0°26'	-0°26'	
-0°21'	-0°20'	-0°11' 0°11'

Rear : Left

Actual	Before	Specified Range
-1°51'	-1°51'	-2°00' 0°00'
-0°10'	-0°10'	0°03' 0°11'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°41'	-1°42'	-2°00' 0°00'
0°14'	0°13'	0°03' 0°11'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
-0°10'	-0°09'	
0°04'	0°03'	0°05' 0°21'
-0°12'	-0°11'	
0mm	0mm	