



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: TAN JUN HONG			Ref: CS3/ASM21005931/R1qce2 Date: 27/05/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 8979M	Veh. Inspected	GBC 2506E
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03A8X	Excess (\$)	0.00
	Assign From	TAN JUN HONG	Assign Date	18/05/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150 M	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	JTFAT35YX0K201640	Colour	BLUE
	Odometer	496567 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	MICHELIN	7 mm
	L/H Front Tyre	195 R15C	MICHELIN	7 mm
	R/H Rear Tyre	155 R12C (D)	MICHELIN	5/5 mm
	L/H Rear Tyre	155 R12C (D)	MICHELIN	5/5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.			
5. General Information				
	Accident Date	17/05/2021	Inspect Date / Time	19/05/2021 ( 04:00 PM )
	Survey held at	5 SOON LEE STREET #06-36 PIONEER POINT		
	Repairer	TAI TIONG AUTO MOBIL TRADING		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	

Report Ref No. CS3/ASM21005931/R1qce2

Inspected By

*MRB*

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

*KK*

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or  
relying on this Report, in whole or in part, does so at his or her own risk.