



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL RENT-A-CAR PTE LTD			Ref: CS/TP21005957/Uqf3e2	
BLK 1 KAKI BUKIT AVE 6 BLK C			Date: 01/06/2021	
#01-56 AUTOBAY @KAKI BUKITSINGAPORE				
417883				
ON BEHALF OF GOBLIN GROUP PTE LTD			Code: TP533	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		SMN 9775K
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		19/05/2021
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GB71076423	Colour	GREEN	
Odometer	68223 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	FIRENZA	6 mm	
L/H Front Tyre	185/65 R15	FIRENZA	6 mm	
R/H Rear Tyre	185/65 R15	FIRENZA	6 mm	
L/H Rear Tyre	185/65 R15	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date		19/04/2021	Inspection Date	
			19/05/2021	
Survey held at		BLUWEL RENT-A CAR PTE LTD		
		BLK 1 KAKI BUKIT AVE 6		
		#01-56 AUTOBAY @KAKI BUKIT		
		SINGAPORE 417883		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		