



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0427/2021/TF  
**DATE** : 18-May-21  
**WIP** : 26853

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 6/5/2021**

**YOUR INSURED VEH NO : SMC 9757 X**

**CHINA TAIPING INSURANCE (SG) PTE LTD**

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

**Tel: 6389 6541 - Fax: 6224 7175**

*Hi Adrian,*

**3 days - ok - Jy - 30 Jun 21**

**OWNER'S NAME** : MR SEAH WEE JIN, JASON  
**ADDRESS** : 37 PUNGGOL FIELD  
#12-38  
SINGAPORE 828809  
**TELEPHONE** : HP +65 98153275  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 1900014161-02  
**VEHICLE NO** : **SKV 1238 D**  
**MODEL CODE** : A5 SPORTBACK 2.0 TFSI S tronic  
**MODEL YEAR** : 14/2/2019  
**ENGINE NO** : CVK 076459  
**CHASSIS NO** : WAUZZZF59KA026627  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 7-May-21  
**PLACE OF ACCIDENT** : KPE TUNNEL, BEFORE PIE EXIT



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 1238 D**

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	\$	<b>360.00</b>
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,200.00	\$	<b>800.00</b>
3	TO RESPRAY REAR BUMPER.	\$	1,000.00	\$	<b>800.00</b>
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	<b>192.00</b>
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 2,752.00</b>	<b>\$</b>	<b>2,152.00</b>

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 1238 D**

			<b>DAMAGED PARTS &amp; PRICES</b>	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,504.00	\$ <b>2,504.00</b>
2	REAR BUMPER FIXING PARTS	1	\$ 165.00	
3	REAR BUMPER SECURING STRIP	1	\$ 223.00	\$ <b>222.50</b>
4	REAR BUMPER CHROME TRIM	1	\$ 1,016.00	\$ <b>1,016.00</b>
5	REAR BUMPER REFLECTOR - LH / RH	2	\$ 82.00	\$ <b>40.70</b>
6	REAR BUMPER CARRIER	1	\$ 940.00	\$ <b>940.00</b>
7	REAR BUMPER CARRIER SEAL	2	\$ 28.00	\$ <b>28.00</b>
8	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 46.00	
9	REAR BUMPER PARKING AID SENSOR	2	TBC	
10	REAR BUMPER PARKING AID SENSOR SEAL RING	4	\$ 14.00	
11	SUNDRIES		\$ 200.00	
<b>TOTAL SPARE PARTS</b>			<b>\$ 5,218.00</b>	\$ <b>4,751.20</b>
<b>TOTAL LABOUR CHARGES</b>			<b>\$ 2,752.00</b>	\$ <b>2,152.00</b>
<b>GRAND TOTAL</b>			<b>\$ 7,970.00</b>	\$ <b>6,903.20</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT