

Car-in 9/6/21

mp = 26853

PREMIUM AUTOMOBILES

Veron.

Kiam/keang 

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 1238 D

Adrian

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>del d</i>	1	S 2,504.00	✓ 2504
2	REAR BUMPER FIXING PARTS <i>Not in</i>	1	S 165.00	+
3	REAR BUMPER SECURING STRIP <i>new</i>	1	S 223.00	✓ 222.50
4	REAR BUMPER CHROME TRIM <i>cut</i>	1	S 1,016.00	✓ 1016
5	REAR BUMPER REFLECTOR - LH <i>(RH) Not in RH and</i>	2	S 82.00 41	40.70
6	REAR BUMPER CARRIER <i>Not in Best</i>	1	S 940.00	✓ 940
7	REAR BUMPER CARRIER SEAL <i>Not in New</i>	2	S 28.00	✓ 28
8	REAR BUMPER GUIDE SECTION - LH / RH <i>Not in</i>	2	S 46.00	+
9	REAR BUMPER PARKING AID SENSOR <i>Not in</i>	2	TBC	+
10	REAR BUMPER PARKING AID SENSOR SEAL RING <i>Not in</i>	4	S 14.00	+
11	SUNDRIES		S 200.00	7 X
TOTAL SPARE PARTS		:	\$ 5,218.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	
GRAND TOTAL		:	\$ 7,970.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Adrian Lij
Stg.