



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CHAN KIAN CHUAN			Ref: CC4/ASM21005986/Gpa3q2 Date: 14/01/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 6270S	Veh. Inspected	SJR 3225K	
Policy No.	P2426680	Coverage (\$)	0.00	
Claim No.	S1M03A99	Excess (\$)	0.00	
Assign From		Assign Date	19/05/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA NOAH HYBRID 1.8X	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZWR800329907	Colour	WHITE	
Odometer	104410 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	GOODYEAR	6 mm	
L/H Front Tyre	215/50 R17	GOODYEAR	6 mm	
R/H Rear Tyre	215/50 R17	GOODYEAR	6 mm	
L/H Rear Tyre	215/50 R17	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	17/05/2021	Inspection Date	19/05/2021	
Survey held at	DETAIL LAB BLK 8 KAKI BUKIT AVE 4 #02-03/04 PREMIER @ KB SINGAPORE 415875			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	